

## Coast Guard (Great Lakes Pilotage), DHS

## § 401.300

his or her license and/or MMC to the U.S. Coast Guard. If the license or officer endorsement is suspended, the Certificate of Registration will be held with the suspended license or officer endorsement and returned to the holder upon expiration of the suspension period.

[32 FR 14221, Oct. 13, 1967, as amended by CGFR 68-57, 33 FR 6478, Apr. 27, 1968; 61 FR 5721, Feb. 14, 1996. Redesignated at 61 FR 32655, June 25, 1996, and further redesignated and amended by USCG-1998-3976, 63 FR 35139, 35140, June 29, 1998; USCG-2002-13058, 67 FR 61279, Sept. 30, 2002; USCG-2006-24371, 74 FR 11267, Mar. 16, 2009]

### § 401.260 Reports.

(a) A marine accident which occurs while a U.S. Registered Pilot is in the service of a vessel in U.S. or Canadian waters of the Great Lakes shall be reported by the Registered Pilot to the Director as soon as possible, but not later than 15 days after the accident. The report shall name and describe the vessel or vessels involved, and shall describe the accident, including type of accident, location, time, prevailing weather, damage to the vessel or vessels or property, and injury to persons or lives lost. This report does not relieve the pilot of responsibility for submitting any report required by other government agencies of the United States or Canada.

(b) Every U.S. Registered Pilot shall file with the Director any change of his or her mailing address within 15 days after the change.

(c) Every authorized pilotage pool of U.S. Registered Pilots rendering pilotage service shall submit, by the 10th day of the month following, a monthly report of availability, on a form provided by the Director, of all U.S. Registered Pilots and Applicant Pilots of that pool. The report shall include the availability of Canadian Registered Pilots who are assigned to that pool for administrative purposes. The report shall list the name of each pilot and show his or her availability status for each day of the month as: available, unavailable due to illness or injury, unavailable with advance notice for personal reasons, unavailability authorized by the pool for business reasons, unavailable without advance notice or

unaccounted for, unavailable for disciplinary reasons. The report shall be maintained on a daily basis by an officer or employee of the pool, who shall be responsible for the completeness and accuracy of the report.

[31 FR 9065, July 1, 1966; 32 FR 14221, Oct. 13, 1967. Redesignated at 61 FR 32655, June 25, 1996, and further redesignated by USCG-1998-3976, 63 FR 35139, June 29, 1998; USCG-2002-13058, 67 FR 61279, Sept. 30, 2002]

## Subpart C—Establishment of Pools by Voluntary Associations of United States Registered Pilots

### § 401.300 Authorization for establishment of pools.

(a) Voluntary associations of U.S. registered pilots will be authorized to establish a pool or pools in the following areas of the U.S. waters of the Great Lakes designated by the President in Proclamation No. 3385 of December 22, 1960, as amended by Proclamation No. 3855 of June 10, 1968, or in such other areas as the Director may deem necessary to assure adequate and efficient pilotage services for the U.S. waters of the Great Lakes:

(1) *District No. 1.* All United States waters of the St. Lawrence River between the international boundary at St. Regis and a line at the head of the river running (at approximately 127° True) between Carruthers Point Light and South Side Light extended to the New York shore.

(2) *District No. 2.* All United States waters of Lake Erie westward of a line running (at approximately 026° True) from Sandusky Pierhead Light at Cedar Point to Southeast Shoal Light; all waters contained within the arc of a circle of one mile radius eastward of Sandusky Pierhead Light; the Detroit River; Lake St. Clair; the St. Clair River, and Northern approaches thereto south of latitude 43°05'30" N.

(3) *District No. 3.* All U.S. waters of the St. Marys River, Sault Sainte Marie Locks and approaches thereto between latitude 45°59' N. at the southern approach and longitude 84°33' W. at the northern approach.

(b) The Director shall determine the number of pools that will be authorized