

preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption ADDRESSES. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 95-SW-03-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final

regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

95-10-08 CALIFORNIA DEPARTMENT OF FORESTRY; ERICKSON AIR-CRANE CO.; GARLICK HELICOPTERS; HAWKINS AND POWERS AVIATION, INC.; INTERNATIONAL HELICOPTERS, INC.; SMITH HELICOPTERS; SOUTHWEST FLORIDA AVIATION; WEST COAST FABRICATIONS; WESTERN INTERNATIONAL AVIATION, INC.; WILLIAMS HELICOPTER TECHNOLOGY, INC.; AND, UNC HELICOPTERS: Amendment 39-9225. Docket No. 95-SW-03-AD.

Applicability: Model UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, UH-1P, TH-1F, and TH-1L helicopters, with a 42-degree tail rotor drive gearbox assembly (42-degree gearbox), part number (P/N) 204-040-003-023, or -037, installed, certificated in the restricted category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (e) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the 42-degree gearbox, loss of tail rotor control, and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight, after the effective date of this AD, verify that the tail rotor control system is rigged in accordance with the applicable maintenance manual.

(b) Before further flight, and thereafter at intervals not to exceed 400 torque events, disassemble the affected 42-degree gearbox and inspect for cracks at the roots of the gear teeth on the pinion, P/N 204-040-500-007 or -009, and gear, P/N 204-040-500-008 or -010, using a fluorescent penetrant inspection method in accordance with the applicable maintenance manual. Only post emulsified fluorescent penetrant inspection materials (Type I, Method B or D, Sensitivity Level 3 or greater) are approved for use. A torque event is defined as a takeoff or a lift (internal or external).

(c) If any crack is found at the roots of the gear teeth on the pinion or gear, replace the pinion or gear with an airworthy pinion or gear in accordance with the applicable maintenance manual.

(d) Create a component history card for the 42-degree gearbox. Record the number of torque events on a daily basis.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, Rotorcraft Certification Office, FAA, Rotorcraft Directorate. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(g) This amendment becomes effective on May 26, 1995.

Issued in Fort Worth, Texas, on May 4, 1995.

Mark R. Schilling,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 95-11540 Filed 5-10-95; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 97

[Docket No. 28214; Amdt. No. 1662]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
2. The FAA Regional Office of the region in which the affected airport is located; or
3. The Flight Inspection Area Office which originated the SIAP.

For Purchase

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Paul J. Best, Flight Procedures Standards Branch (AFS-420), Technical Programs Division, Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone (202) 267-8277.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or

revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Approach Procedures (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists

for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Navigation (Air).

Issued in Washington, DC on May 5, 1995.

Thomas C. Accardi,

Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. app. 1348, 1354(a), 1421 and 1510; 49 U.S.C. 106(g); and 14 CFR 11.49(b)(2).

2. Part 97 is amended to read as follows:

§§ 97.23, 97.25, 97.27, 97.29, 97.31, 97.33, 97.35 [Amended]

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, identified as follows:

* * * *Effective June 22, 1995*

Springdale, AR, Springdale Muni, VOR/DME or GPS RWY 36, Amdt 8
Brazil, IN, Brazil Clay County, VOR or GPS RWY 9, Amdt 7
Griffith, IN, Griffith-Merrillville, VOR or GPS RWY 8, Amdt 7

Logansport, IN, Logansport Muni, VOR-A, Amdt 7

Logansport, IN, Logansport Muni, NDB RWY 9, Amdt 2

Logansport, IN, Logansport Muni, VOR/DME RNAV RWY 27, Amdt 3

Marion, IN, Marion Muni, VOR RWY 22, Amdt 1

Marion, IN, Marion Muni, VOR RWY 15, Amdt 9

Marion, IN, Marion Muni, VOR RWY 4, Amdt 12

Marion, IN, Marion Muni, ILS RWY 4, Amdt 6

Rochester, IN, Fulton County, NDB RWY 29, Amdt 10

Sheridan, IN, Sheridan, VOR/DME-A, Amdt 6

Terre Haute, IN, Sky King, VOR or GPS-A, Amdt 6

Teterboro, NJ, Teterboro, ILS RWY 6, Amdt 27

Pryor Creek, OK, Mid-America Industrial, VOR/DME or GPS-A, Amdt 4, Cancelled

Pryor Creek, OK, Mid-America Industrial, VOR/DME or GPS-A, Orig

Chetek, WI, Chetek Muni-Southworth, VOR/DME or GPS RWY 17, Amdt 2

Ladysmith, WI, Rusk County, NDB or GPS RWY 32, Amdt 2

Siren, WI, Burnett County, VOR or GPS RWY 4, Amdt 2

Solon Springs, WI, Solon Springs Muni, NDB RWY 19, Amdt 1

* * * *Effective 20 July, 1995*

Riverside, CA, Riverside Muni, VOR or GSP-A, Amdt 5

Campbellsville, KY, Taylor County, SDF RWY 23, Amdt 2

Campbellsville, KY, Taylor County, NDB or GPS RWY 23, Amdt 3

Campbellsville, KY, Taylor County, VOR/DME or GSP-A, Amdt 5

Bedford, MA, Laurence G Hanscom Fld, NDB RWY 11, Amdt 20

Bedford, MA, Laurence G Hanscom Fld, NDB or GPS RWY 29, Amdt 6

Bedford, MA, Laurence G Hanscom Fld, ILS RWY 11, Amdt 23

Bedford, MA, Laurence G Hanscom Fld, ILS RWY 29, Amdt 4

Newark, NJ, Newark Intl, GPS RWY 11, Orig

McMinnville, TN, Warren County Memorial, LOC RWY 23, Amdt 1

McMinnville, TN, Warren County Memorial, NDB or GPS RWY 23, Amdt 1

Green Bay, WI, Austin Straubel International, VOR or GPS RWY 12, Amdt 18

Green Bay, WI, Austin Straubel International, VOR/DME or TACAN or GPS RWY 36, Amdt 7

Green Bay, WI, Austin Straubel International, LOC BC RWY 24, Amdt 17

Green Bay, WI, Austin Straubel International, NDB or GPS RWY 6, Amdt 16

Green Bay, WI, Austin Straubel International, ILS RWY 6, Amdt 20

Green Bay, WI, Austin Straubel International, ILS RWY 36, Amdt 6

Green Bay, WI, Austin Straubel International, RADAR-1, Amdt 8

[FR Doc. 95-11670 Filed 5-10-95; 8:45 am]

BILLING CODE 4910-13-M

14 CFR Part 97

[Docket No. 28215; Amdt. No. 1663]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

For Purchase

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Paul J. Best, Flight Procedures Standards Branch (AFS-420), Technical Programs

Division, Flight Standards Service, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone (202) 267-8277.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAM for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been cancelled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Approach Procedures (TERPS). In developing these charge changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the