

stormwater management, archaeological and historic resources, ecological issues. Environmental and social impacts proposed for analysis include land use and neighborhood impacts, traffic and parking impacts near stations, visual impacts, impacts on cultural resources, and noise and vibration impacts. Impacts on natural areas, rare and endangered species, air and water quality, groundwater and potentially contaminated sites will also be covered. The impacts will be evaluated both for the construction period and for the long-term period of operation. Measures to mitigate any significant adverse impact will be developed.

Issued on: November 19, 1996.

Susan E. Schruth,

Regional Administrator.

[FR Doc. 96-29948 Filed 11-21-96; 8:45 am]

BILLING CODE 4910-57-P

National Highway Traffic Safety Administration

[Docket No. 96-119; Notice 1]

Michelin North America, Inc.; Receipt of Application for Decision of Inconsequential Noncompliance

Michelin North America, Inc. (Michelin) of Greenville, South Carolina, has determined that some of its tires fail to comply with the labeling requirements of 49 CFR 571.119, Federal Motor Vehicle Safety Standard (FMVSS) No. 119, "New Pneumatic Tires for Vehicles Other Than Passenger Cars," and has filed an appropriate report pursuant to 49 CFR Part 573, "Defect and Noncompliance Reports." Michelin has also applied to be exempted from the notification and remedy requirements of 49 U.S.C. Chapter 301—"Motor Vehicle Safety" on the basis that the noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of an application is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the application.

FMVSS No. 119, Paragraph S6.5, Tire markings, requires that tires be marked on each sidewall with specific information. The markings shall be placed between the maximum section width (exclusive of sidewall decorations or curb ribs) and the bead on at least one sidewall, unless the maximum section width of the tire is located in an area which is not more than one-fourth of the distance from the bead to the shoulder of the tire. If the maximum section width falls within that area, the

markings shall appear between the bead and a point one-half the distance from the bead to the shoulder of the tire, on at least one sidewall.

Michelin's description of non-compliance follows: "During the period of the 48th week of 1995 through the 1st week of 1996, the Opelika, Alabama, plant of Uniroyal Goodrich Tire Manufacturing, a division of Michelin North America, Inc., produced tires with the markings required by 49 CFR § 571.119 S6.5 (f) and (g) marked only on one side of the tire. Additionally, on the same side of the tire as the missing information, the word "Radial" as required by S6.5(i) appears above the maximum section width instead of between the maximum section width and the bead. However, all marking on the opposite side of the tire meets the requirements of S6.5. Furthermore, all performance requirements of FMVSS #119 are met or exceeded.

"Approximately 1,041 LT245/75R16 Uniroyal Laredo LTL LR E tires were produced without the aforementioned information on one sidewall of the tire. Of this total, as many as 559 were shipped to an Original Equipment Vehicle Manufacturer or to the replacement market. The remaining 482 tires have been isolated in our warehouses and will be brought into full compliance with the marking requirements of FMVSS #119 or scrapped."

Michelin supported its application for inconsequential noncompliance with the following:

"[Michelin] does not believe that this minor error on the one tire sidewall will impact motor vehicle safety:

"1. The marking of number and composition of ply cord material required by S6.5(f) is contained on one side of the tire instead of both sides. When previously granting a petition for inconsequential noncompliance (see e.g., Bridgestone, IP82-8, 47 FR 51269, November 12, 1982) NHTSA has concluded that "...the number of plies, and the composition of the ply material had an inconsequential relationship to motor vehicle safety..." and has stated that "...the failure to state the number of plies and composition of ply material is an informational failure and does not affect the ability of the tires to meet the performance requirements...."

"2. The absence of the word "tubeless" on one tire sidewall (as required by S6.5(g) for both sidewalls) will not impact motor vehicle safety since it is merely an informational failure on one sidewall and does not impact tire performance. The tires in question are only produced in a "tubeless" configuration. However,

should these tires be mounted with a tube, performance of the tires would be perfectly satisfactory.

"3. The word "radial" on one sidewall of the tire appears above the maximum section width instead of between the bead and maximum section width. Again, this does not affect the ability of the tire to perform. Additionally, the "R" located in the size designation LT245/75R16 which is marked between the bead and sidewall is recognized by the International Standards Organization, the Tire and Rim Association, the Rubber Manufacturers Association and others, including the general public, as being the standard designation for a radial tire. Thus it would be obvious to anyone looking at either sidewall of this tire that it was indeed a radial tire."

Interested persons are invited to submit written data, views, and arguments on the application of Michelin, described above. Comments should refer to the docket number and be submitted to: Docket Section, National Highway Traffic Safety Administration, Room 5109, 400 Seventh Street, SW., Washington, D.C., 20590. It is requested but not required that six copies be submitted.

All comments received before the close of business on the closing date indicated below will be considered. The application and supporting materials, and all comments received after the closing date, will also be filed and will be considered to the extent possible. When the application is granted or denied, the notice will be published in the Federal Register pursuant to the authority indicated below. Comment closing date: December 23, 1996.

(49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.50 and 501.8)

Issued on: November 18, 1996.

L. Robert Shelton,

Associate Administrator for Safety Performance Standards.

[FR Doc. 96-29949 Filed 11-21-96; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF VETERANS AFFAIRS

Advisory Committee on Women Veterans, Notice of Meeting

The Department of Veterans Affairs gives notice under Public Law 92-463 that a meeting of the Advisory Committee on Women Veterans will be held December 3-5, 1996, at the Department of Veterans Affairs, in Washington, DC. The purpose of the Advisory Committee on Women