

interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-SW-43-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g) 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

#### AD 98-19-13 Bell Helicopter Textron

**Canada:** Amendment 39-10990. Docket No. 98-SW-43-AD.

**Applicability:** Model 407 helicopters, with engine-to-transmission driveshaft (driveshaft), part number (P/N) 206-340-300-103, installed, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

**Compliance:** Required prior to or upon accumulating 50 hours total time-in-service (TIS) on driveshaft, P/N 206-340-300-103.

To prevent failure of the driveshaft, which could result in loss of engine drive to the rotor system, damage to critical structural components, and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove driveshaft, P/N 206-340-300-103, and replace it with an airworthy driveshaft, P/N 206-340-300-105. Driveshaft, P/N 206-340-300-103, must not be installed on any helicopter.

**Note 2:** Bell Helicopter Textron Alert Service Bulletin No. 407-98-19, dated June 19, 1998, pertains to the subject of this AD. Removed driveshaft, P/N 206-340-300-103, should be destroyed.

(b) This AD revises the Airworthiness Limitations section of the maintenance manual by establishing a retirement life of 5,000 hours TIS for driveshaft, P/N 206-340-300-105. A component record card or equivalent record for this P/N must also be established.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

(d) Special flight permits will not be issued.

(e) This amendment becomes effective on January 27, 1999. To all persons except those persons to whom it was made immediately effective by Priority Letter AD 98-19-13, issued September 2, 1998, which contained the requirements of this amendment.

**Note 4:** The subject of this AD is addressed in Transport Canada (Canada) AD CF-98-25, August 25, 1998.

Issued in Fort Worth, Texas, on January 5, 1999.

**Henry A. Armstrong,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 99-615 Filed 1-11-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 98-AWP-32]

#### Revocation of Class E Airspace, Victorville, George AFB, CA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule

**SUMMARY:** This action will revoke the Class E airspace at Victorville, George Air Force Base (AFB), CA. In order to meet federal mandates with regard to Base Realignment and Closure (BRAC), the U.S. Air Force ceased air operations at George AFB in December 1992, thereby eliminating the criteria for Class E airspace.

**EFFECTIVE DATE:** 0901 UTC March 25, 1999.

**FOR FURTHER INFORMATION CONTACT:** Debra Trindle, Air Traffic Division, Airspace Specialist, AWP-520.10, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725-6613.

#### SUPPLEMENTARY INFORMATION:

#### History

In order to meet federal mandates with regard to Base Realignment and Closure, the U.S. Air Force ceased air operations at George AFB in December 1992. The intended effect of this action is to revoke the Class E airspace associated with George AFB airspace as published in Paragraph 6005 of FAA Order 7400.9F dated September 10, 1998, and effective September 16, 1998, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be subsequently removed from this Order.

**The Rule**

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) revokes previously designated controlled airspace associated with George AFB.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; ROUTES; AND REPORTING POINTS**

1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389; 14 CFR 11.69.

**§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9F, Airspace Designations and Reporting Points, dated September 10, 1998, and effective September 16, 1998, is amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

**AWP CA E5 Victorville, George AFB, CA [Removed]**

\* \* \* \* \*

Issued in Los Angeles, California, on December 28, 1998.

**John Clancy,**

*Manager, Air Traffic Division, Western-Pacific Region.*

[FR Doc. 99–649 Filed 1–11–99; 8:45 am]

BILLING CODE 4910–13–M

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 97**

[Docket No. 29430; Amdt. No. 1903]

RIN 2120–AA65

**Standard Instrument Approach Procedures; Miscellaneous Amendments**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference—approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

**For Examination**

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

**For Purchase**

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

**By Subscription**

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

**FOR FURTHER INFORMATION CONTACT:**

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS–420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169. (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) telephone: (405) 954–4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 14 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

**The Rule**

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific