

accomplished prior to July 7, 1997, in accordance with Saab Service Bulletin 340-33-040, Revision 01, dated January 31, 1997, also is considered acceptable for compliance with the requirement of paragraph (a)(2) of this AD.

(3) For Model SAAB 2000 series airplanes on which a Page Aerospace lampholder having P/N C756-10-001 is installed: Install a retaining clip in accordance with Saab Service Bulletin 2000-33-009, dated June 19, 1996.

Reinspections Following Replacement or Reinstallation

(b) Following the accomplishment of the requirements of paragraph (a) or paragraph (c) of this AD: If any fluorescent lamp or lampholder is replaced or reinstalled, within 7 days after accomplishing such replacement or reinstallation, reinspect the lamp to ensure it is still in the correct position, in accordance with Saab Service Bulletin 340-33-047, dated May 16, 1997, or Revision 01, dated June 26, 1998 (for Model SAAB 340B series airplanes); or Saab Service Bulletin 2000-33-014, dated May 16, 1997 (for Model SAAB 2000 series airplanes); as applicable. If any lamp is installed incorrectly, prior to further flight, make corrections to ensure correct installation in accordance with the applicable service bulletin.

New Requirements of This AD

Inspections for Additional Airplanes

(c) For airplanes other than those specified in paragraph (a) of this AD: Within 30 days after the effective date of this AD, accomplish the requirements of paragraph (a) of this AD, and thereafter accomplish the requirements of paragraph (b) of this AD.

Terminating Modification

(d) For all airplanes: Within 18 months after the effective date of this AD, accomplish the requirements of paragraph (d)(1) or (d)(2) of this AD, as applicable. Accomplishment of the actions required by the applicable paragraph constitutes terminating action for the requirements of this AD.

(1) For Model SAAB 340B series airplanes: Replace the electronic light ballasts with improved ballasts, in accordance with Saab Service Bulletin 340-33-048, Revision 01, dated January 21, 1999. Concurrent with the replacement, modify the ballasts to ensure sufficient clearance between the ballast and certain transistors, in accordance with Saab Service Bulletin 340-33-049, Revision 02, dated February 2, 2000.

(2) For Model SAAB 2000 series airplanes: Replace the electronic light ballasts with improved ballasts, in accordance with Saab Service Bulletin 2000-33-015, dated January 29, 1999.

Note 3: Modification of the ballasts for sufficient clearance in accordance with Saab Service Bulletin 340-33-049, Revision 01, dated November 15, 1999, is acceptable for compliance with the modification requirement of paragraph (d)(1) of the AD.

Spares

(e) As of the effective date of this AD, no person shall install a fluorescent lampholder

having Page Aerospace P/N D756-02-001 or Page Aerospace P/N C756-10-001 on any Model SAAB 340B or SAAB 2000 series airplane, unless the lampholder has been modified in accordance with the requirements of paragraph (a)(2) or (a)(3) of this AD, as applicable.

Alternative Methods of Compliance

(f)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 97-13-06, amendment 39-10052, are approved as alternative methods of compliance with this AD.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(g) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 5: The subject of this AD is addressed in Swedish airworthiness directives 1-113R1 and 1-114R1, both dated September 8, 1998.

Issued in Renton, Washington, on June 7, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-14883 Filed 6-12-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-AAL-4]

Proposed Revision of Class E Airspace; Ambler, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action revises Class E airspace at Ambler, AK. The establishment of a Global Positioning System (GPS) instrument approach to runway (RWY) 36 at Ambler, AK, has made this action necessary. Adoption of this proposal would result in the provision of adequate controlled

airspace for Instrument Flight Rules (IFR) operations at Ambler, AK.

DATES: Comments must be received on or before July 28, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Operations Branch, AAL-530, Docket No. 00-AAL-4, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587.

The official docket may be examined in the Office of the Regional Counsel for the Alaskan Region at the same address.

An informal docket may also be examined during normal business hours in the Office of the Manager, Operations Branch, Air Traffic Division, at the address shown above and on the Internet at Alaskan Region's homepage at <http://www.alaska.faa.gov/at> or at address <http://162.58.28.41/at>.

FOR FURTHER INFORMATION CONTACT: Bob Durand, Operations Branch, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587; telephone number (907) 271-5898; fax: (907) 271-2850; email: Bob.Durand@faa.gov. Internet address: <http://www.alaska.faa.gov/at> or at address <http://162.58.28.41/at>.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 00-AAL-4." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Operations Branch, Air Traffic Division, Federal Aviation

Administration, 222 West 7th Avenue, Box 14, Anchorage, AK, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of Notice of Proposed Rulemaking's (NPRM's)

An electronic copy of this document may be downloaded, using a modem and suitable communications software, from the FAA regulations section of the Fedworld electronic bulletin board service (telephone: 703-321-3339) or the Federal Register's electronic bulletin board service (telephone: 202-512-1661).

Internet users may reach the Federal Register's web page for access to recently published rulemaking documents at http://www.access.gpo.gov/su_docs/aces/aces140.html.

Any person may obtain a copy of this NPRM by submitting a request to the Operations Branch, AAL-530, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should contact the individual(s) identified in the **FOR FURTHER INFORMATION CONTACT** section.

The Proposal

The FAA proposes to amend 14 CFR part 71 by revising Class E airspace at Ambler, AK, due to the establishment of a new GPS instrument approach procedure to RWY 36. The intended effect of this proposal is to provide additional controlled airspace for IFR operations at Ambler, AK.

The area would be depicted on aeronautical charts for pilot reference. The coordinates for this airspace docket are based on North American Datum 83. The Class E airspace areas designated as 700/1200 foot transition areas are published in paragraph 6005 in FAA Order 7400.9G, *Airspace Designations and Reporting Points*, dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant

regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9G, *Airspace Designations and Reporting Points*, dated September 1, 1999, and effective September 16, 1999, is amended as follows:

* * * * *

Paragraph 6005 Class E airspace extending upward from 700 feet or more above the surface of the earth.

* * * * *

AAL AK E5 Ambler, AK [Revised]

Ambler Airport, AK
(Lat. 67°06'22" N, long. 157°51'13" N)
Ambler NDB
(Lat. 67°06'24" N, long. 157°51'29" W)

That airspace extending upward from 700 feet above the surface within a 6.3-mile radius of the Ambler Airport and within 3.5 miles each side of the 193° bearing of the Ambler NDB extending from the 6.3-mile radius to 7.2 miles southwest of the airport; and that airspace extending upward from 1,200 feet above the surface within 4 miles west and 8 miles east of the Ambler NDB 193° bearing extending from the NDB to 20 miles southwest of the NDB, and 4 miles either side of a line from lat. 66°20'57" N, long., 158°54'51" W to lat. 66°56'52" N, long. 158°01'13" W and 4 miles either side of a line

from lat. 66°51'40" N, long. 158°55'07" W to lat. 66°56'52" N, long. 158°01'13" W.

* * * * *

Issued in Anchorage, AK, on June 6, 2000.

Willis C. Nelson,

Manager, Air Traffic Division, Alaskan Region.

[FR Doc. 00-14862 Filed 6-12-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF EDUCATION

34 CFR Part 75

RIN 1880-AA02

Direct Grant Programs

AGENCY: Office of the Chief Financial Officer, Department of Education.

ACTION: Notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document reopens the comment period for the proposed amendments to part 75 of the Education Department General Administrative Regulations (EDGAR) that would implement new options for the Department of Education's application review process for discretionary grants. On April 17, 2000 we published in the **Federal Register** (65 FR 20698) a notice of proposed rulemaking proposing amendments to part 75 of EDGAR. The deadline for comments on the proposed regulations was June 1, 2000. We are reopening the original 45-day comment period for the proposed regulations until June 30, 2000, because we have received requests to give stakeholders more time to comment on the proposed changes.

DATES: We must receive your comments on or before June 30, 2000.

ADDRESSES: All comments concerning the proposed regulations should be addressed to: Valerie A. Sinkovits, U.S. Department of Education, 400 Maryland Avenue, SW., room 3652, ROB-3, Washington, DC 20202-4838. If you prefer to send your comments through the Internet, use the following address: comments@ed.gov. You must include the term “Redesign” in the subject line of your electronic message.

FOR FURTHER INFORMATION CONTACT: Valerie Sinkovits, Telephone: (202) 708-7568. If you use a telecommunications device for the deaf (TDD), you may call the Federal Information Relay Service (FIRS) at 1-800-877-8339.

Individuals with disabilities may obtain this document in an alternate format (e.g., Braille, large print, audiotope, or computer diskette) on