

TABLE 804.—MANDATORY INSPECTION REQUIREMENTS

Part nomenclature	Manual/chapter, section/subject	Mandatory, inspection
Fan Disk (all)	72-21-00, INSPECTION	All areas (FPI) ¹ Bores (ECI) ²
Stage 1 high pressure turbine (HPT) Rotor Disk (all) (FPI) ¹	72-46-00, INSPECTION	All areas Bores (ECI) ² Boltholes (ECI) ² Air Holes (ECI) ²
Stage 2 HPT Rotor Disk (all)	72-46-00, INSPECTION	All Areas (FPI) ¹ Bores (ECI) ² Boltholes (FPI) ¹ Air Holes (FPI) ¹
(a) Boltless Rim Configuration	Boltholes (ECI) ² Air Holes (ECI) ²
(b) Bolted Rim Configuration	All areas (FPI) ¹ Bore (ECI) ²
HPT Rotor Outer Torque Coupling (all)	72-46-00, INSPECTION	All areas (FPI) ¹ Bore (ECI) ²

¹ FPI=Fluorescent Penetrant Inspection Method
² ECI=Eddy Current Inspection

(b) Except as provided in paragraph (c) of this AD, and notwithstanding the provisions of section 43.16 of the Federal Aviation Regulations (14 CFR 43.16), these mandatory inspections shall be performed only in accordance with the CF34 Engine Maintenance Program, Chapter 5-21-00, of the General Electric Company, CF34 Series Turbofan Engine Manual, SEI-756.

Alternative Method of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector (PMI), who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Continuous Airworthiness Maintenance Program

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record keeping requirement of § 121.369(c) of the Federal Aviation Regulations [14 CFR 121.369(c)] must maintain records of the mandatory inspections that result from revising the CF34 Engine Maintenance Program and the air carrier's continuous airworthiness program. Alternately, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by

§ 121.369(c) of the Federal Aviation Regulations [14 CFR 121.369(c)]; however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under 121.380(a)(2)(vi) of the Federal Aviation Regulations [14 CFR 121.380(a)(2)(vi)]. All other operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the engine manual changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the Engine Maintenance Program requirements specified in the GE CF34 Series Turbofan Engine Manual.

Issued in Burlington, Massachusetts, on August 11, 2000.

David A. Downey,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 00-21054 Filed 8-17-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ASO-28]

Proposed Amendment of Class E Airspace; Picayune, MS.

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend Class E airspace at Picayune, Ms. The Picayune—Pearl River County Airport has closed and a new airport has been established approximately 3.5 miles southeast of the Picayune—Pearl River County Airport site. The name of

the new airport is Picayune Municipal Airport. Area Navigation (RNAV) Runway (RWY) 18 and RWY 36 Standard Instrument Approach Procedures (SIAP) have been developed for Picayune Municipal Airport. As a result, controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate the SIAP at Picayune Municipal Airport.

DATES: Comments must be received on or before September 18, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Docket No. 00-ASO-28, Manager, Airspace Branch, ASO-520, P.O. Box 20636, Atlanta, Georgia 30320.

The official docket may be examined in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, telephone (404) 305-5627.

FOR FURTHER INFORMATION CONTACT: Nancy B. Shelton, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be

submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 00-ASO-28." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Manager, Airspace Branch, ASO-520, Air Traffic Division, P.O. Box 20636, Atlanta, Georgia 30320. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A which describes the application procedure.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR Part 71) to amend Class E airspace at Picayune, MS. The Picayune—Pearl River County Airport has closed and a new airport has been established approximately 3.5 miles southeast of the Picayune—Pearl River County Airport site. The name of the new airport is Picayune Municipal Airport. RNAV RWY 18 and RWY 36 SIAPs have been developed for Picayune Municipal Airport. Controlled airspace extending upward from 700 feet AGL is needed to accommodate the SIAPs at Picayune Municipal Airport. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface are published in Paragraph 6005 of FAA Order 7400.9G, dated September 1, 1999, and effective September 16, 1999, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document

would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9F, Airspace Designations and Reporting Points, dated September 1, 1999, and effective September 16, 1999, is amended as follows: Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth.

* * * * *

ASO MS E5 Picayune, MS [Revised]

Picayune Municipal Airport, MS (Lat. 30°29'15"N, long 89°39'04"W)

That airspace extending upward from 700 feet or more above the surface within a 6.5-mile radius of the Picayune Municipal Airport; excluding that airspace within the Bay St. Louis, MS, Class E airspace area and that airspace within the Slidell, LA, Class E airspace area.

* * * * *

Issued in College Park, Georgia, on July 26, 2000.

Marvin A. Burnette,

*Acting Manager, Air Traffic Division,
Southern Region.*

[FR Doc. 00-19837 Filed 8-17-00; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

23 CFR Part 658

[FHWA Docket No. 1997-2234 (formerly 87-5 and 89-12)]

RIN 2125-AC30

Truck Length and Width Exclusive Devices

AGENCY: Federal Highway Administration (FHWA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); request for comments.

SUMMARY: The FHWA is requesting comments on proposed criteria for excluding safety or efficiency enhancing devices from measurement of vehicle length and width.

All previous interpretations related to exclusions from measurements of vehicle length and width would be superseded to the extent they are inconsistent with these regulations.

DATES: Comments must be received on or before November 16, 2000.

ADDRESSES: Mail or hand deliver comments to docket number 1997-2234, U.S. Department of Transportation, Dockets Management Facility, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590, or submit electronically at <http://dmses.dot.gov/submit>. All comments received will be available for examination and copying at the above address from 9 a.m. to 5 p.m., e.t., Monday through Friday, except Federal Holidays. Those desiring notification of receipt of comments must include a self-addressed, stamped postcard or print the acknowledgment page after submitting comments electronically.

FOR FURTHER INFORMATION CONTACT: Mr. Tom Klimek, Office of Freight Management and Operations, (202-366-2212); or Mr. Charles Medalen, Office of the Chief Counsel (202-366-1354), Federal Highway Administration, 400 Seventh Street, SW., Washington, DC 20590. Office hours are from 7:45 a.m. to 4:15 p.m., e.t., Monday through Friday, except Federal holidays.

SUPPLEMENTARY INFORMATION: