

Action	Compliance time	Procedures
(1) Deactivate the windshield spray nozzle heating elements by cutting wire ME16F20 at the splice at frame 7. Cap (MS2574-2 caps) and stow cables.	Within the next 100 hours time-in-service (TIS) after April 6, 2001 (the effective date of this AD), unless already accomplished.	Dornier All Operators Telefax (AOT) No. AOT-228-30-022, dated September 9, 1998, references this action.
(2) Do not install, on any affected airplane, windshield spray nozzle option SCN 3109.	As of April 6, 2001 (the effective date of this AD).	Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Karl M. Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may obtain copies of the documents referenced in this AD from Dornier Luftfahrt GmbH, Product Support, P.O. Box 1103, D-82230 Wessling, Federal Republic of Germany; telephone: (08153) 302631; facsimile: (08153) 304463. You may examine these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note 2: The subject of this AD is addressed in German AD Number 1999-030/2, dated April 8, 1999.

(i) *When does this amendment become effective?* This amendment becomes effective on April 6, 2001.

Issued in Kansas City, Missouri, on February 8, 2001.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-4048 Filed 2-20-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Part 117

[CGD01-01-010]

Drawbridge Operation Regulations: Hackensack River, NJ

AGENCY: Coast Guard, DOT.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, First Coast Guard District, has issued a temporary deviation from the drawbridge operation regulations governing the operation of the Lincoln Highway Bridge, at mile 1.8, across the Hackensack River at Jersey City, New Jersey. This deviation authorizes the bridge owner to operate the bridge from February 12, 2001 through April 10, 2001, as follows: The draw shall open on signal; except that, Monday through Thursday, 9 a.m. to 4 p.m., at least a one-hour advance notice for bridge openings is required and from 9 p.m. on Friday through 5 a.m. on Monday, at least a four-hour advance notice for bridge openings is required. This action is necessary to facilitate maintenance at the bridge.

DATES: This deviation is effective from February 12, 2001 through April 10, 2001.

FOR FURTHER INFORMATION CONTACT: Judy Yee, Project Officer, First Coast Guard District, at (212) 668-7165.

SUPPLEMENTARY INFORMATION: The Lincoln Highway Bridge, at mile 1.8, across the Hackensack River, has a vertical clearance of 35 feet at mean high water, and 40 feet at mean low water in the closed position. The existing drawbridge operating regulations require the bridge to open on signal at all times.

The bridge owner, New Jersey Department of Transportation, requested

a temporary deviation from the drawbridge operating regulations to facilitate necessary structural maintenance at the bridge. This deviation from the operating regulations allows the bridge owner to operate the bridge from February 12, 2001 through April 10, 2001, as follows: The draw shall open on signal; except that, Monday through Thursday, 9 a.m. to 4 p.m., at least a one-hour advance notice for bridge openings is required and from 9 p.m. on Friday through 5 a.m. on Monday, at least a four-hour advance notice for bridge openings is required.

Thirty days notice to the Coast Guard for approval of this maintenance repair was not given by the bridge owner and was not required because this work involves vital, unscheduled maintenance that must be performed without undue delay.

Vessels that can pass under the bridge without an opening may do so at all times during the closed period.

In accordance with 33 CFR 117.35(c), this work will be performed with all due speed in order to return the bridge to normal operation as soon as possible. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: January 30, 2001.

G.N. Naccara,

Rear Admiral, U.S. Coast Guard, Commander, First Coast Guard District.

[FR Doc. 01-4227 Filed 2-20-01; 8:45 am]

BILLING CODE 4910-15-U

FEDERAL COMMUNICATIONS COMMISSION

47 CFR Ch. I

[CC Docket No. 99-273; FCC 01-27]

Provision of Directory Listing Information Under the Telecommunications Act of 1934

AGENCY: Federal Communications Commission.

ACTION: Final rule.

SUMMARY: This document adopts some of the tentative conclusions contained in the *Subscriber List Information/Directory Assistance Order and Notice*