

comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 3 helicopters of U.S. registry would be affected by this AD, that it would take approximately 5 work hours per helicopter to replace the shafts, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$19,000 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$57,900.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-12095 (66 FR 8507, February 1, 2001), and by adding

a new airworthiness directive (AD), Amendment 39-12232, to read as follows:

#### AD 2001-10-06 Sikorsky Aircraft

**Corporation:** Amendment 39-12232.  
Docket No. 2001-SW-05-AD.  
Supersedes AD 2000-23-52,  
Amendment 39-12095, Docket No.  
2000-SW-61-AD.

**Applicability:** Model S-76A, S-76B, and S-76C helicopters with main rotor shaft assembly (shaft), part number 76351-09030-all dash numbers, installed, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required before further flight, unless accomplished previously.

To prevent failure of the shaft and subsequent loss of control of the helicopter:

(a) Replace each affected shaft, serial number B015-00700 through B015-00706, with an airworthy shaft.

**Note 2:** Sikorsky Alert Service Bulletin No. 76-66-32A (319A), Revision A, dated January 17, 2001, pertains to the subject of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Boston ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on June 21, 2001.

Issued in Fort Worth, Texas, on May 10, 2001.

**Larry M. Kelly,**

*Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.*

[FR Doc. 01-12336 Filed 5-16-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 30248; Amdt. No. 2051]

#### Standard Instrument Approach Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference—approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

**ADDRESSES:** Available for matter incorporated by reference in the amendment is as follows:

#### For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

**For Purchase—**Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

**By Subscription—**Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

**FOR FURTHER INFORMATION CONTACT:** Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs

Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

**The Rule**

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends,

or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAMs for each SIAP. The SIAP information in some previously designed FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these chart changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only those specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPS. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

**Conclusion**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a

“significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 97**

Air traffic control, Airports, Navigation (air).

Issued in Washington, DC on May 11, 2001.

**L. Nicholas Lacey,**  
*Director, Flight Standards Service.*

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

**PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES**

1. The authority citation for part 97 is revised to read as follows:

**Authority:** 49 U.S.C. 40103, 40113, 40120, 44701; 49 U.S.C. 106(g); and 14 CFR 11.49(b)(2).

2. Part 97 is amended to read as follows:

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

\* \* \* *Effective Upon Publication*

FDC Date	State	City	Airport	FDC No.	Subject
03/02/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/2278	NDB Rwy 27R, Amdt 5
04/12/01 .....	SD	Watertown .....	Watertown Muni .....	1/3577	ILS Rwy 35, Amdt 10 VOR or GPS Rwy 2
04/16/01 .....	VA	Richmond .....	Richmond Intl .....	1/3633	Amdt 5 RNAV (GPS) Rwy 3
04/18/01 .....	WA	Spokane .....	Spokane Intl .....	1/3688	Orig
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3962	ILS Rwy 27R Amdt 33
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3965	ILS Rwy 29 (CAT I, II, III) Amdt 23B
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3967	VOR/DME Rwy 29 Orig
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3968	VOR/DME Rwy 27L Amdt 11
04/26/01 .....	CA	Hayward .....	Hayward Executive .....	1/3969	VOR or GPS-A Amdt 6B
04/26/01 .....	CA	Hayward .....	Hayward Executive .....	1/3970	VOR/DME or GPS-B Amdt 1B
04/26/01 .....	CA	Hayward .....	Hayward Executive .....	1/3971	LOC/DME Rwy 28L Amdt 1A
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3978	ILS Rwy 11 Amdt 4A VOR or GPS Rwy 9R
04/26/01 .....	CA	Oakland .....	Metropolitan Oakland Intl .....	1/3980	Amdt 7A

FDC Date	State	City	Airport	FDC No.	Subject
04/30/01	TX	Dallas-Fort Worth	Dallas-Fort Worth Intl	1/4048	ILS Rwy 36L, Amdt 6A Converging ILS
04/30/01	TX	Dallas-Fort Worth	Dallas-Fort Worth Intl	1/4049	Rwy 36L, Amdt 3C
04/30/01	TX	Mesquite	Mesquite Metro	1/4054	ILS Rwy 17, Amdt 1
04/30/01	TX	Mesquite	Mesquite Metro	1/4056	NDB or GPS Rwy 17, Amdt 5A
04/30/01	TX	Mesquite	Mesquite Metro	1/4057	LOC BC Rwy 35, Amdt 2
04/30/01	HI	Kaunakakai	Molokai	1/4059	VOR or TACAN or GPS-A, Amdt 15A
05/02/01	AR	Carlisle	Carlisle Muni	1/4156	VOR/DME Rwy 9, Amdt 2
05/03/01	OH	Columbus	Rickenbacker Intl	1/4185	HI-ILS Rwy 5R, Amdt 2
05/04/01	CA	Marysville	Yuba County	1/4218	ILS Rwy 14, Amdt 4D
05/07/01	ND	Grand Forks	Grand Forks Intl	1/4257	ILS Rwy 35L, Amdt 11B
05/07/01	WA	Everett	Snohomish County (Paine Field)	1/4272	NDB RWY 16, Amdt 12A
05/07/01	WA	Everett	Snohomish County (Paine Field)	1/4273	GPS Rwy 16R, Orig
05/07/01	WV	Lewisburg	Greenbrier Valley	1/4292	ILS Rwy 4, Amdt 9
05/07/01	ND	Bismarck	Bismarck Muni	1/4297	ILS Rwy 31, Amdt 32A
05/08/01	PW	Babel Thuap Island	Babel Thuap/Kor Or	1/4320	GPS Rwy 27, Amdt 1
05/08/01	PW	Babel Thuap Island	Babel Thuap Island/Kor Or	1/4321	GPS Rwy 9, Amdt 1
05/09/01	VA	Saluda	Hummel Field	1/4328	GPS Rwy 36, Orig
05/09/01	MN	Duluth	Duluth Intl	1/4354	GPS Rwy 21, Orig
05/09/01	TX	Cleveland	Cleveland Muni	1/4368	GPS Rwy 16, Orig
05/09/01	WA	Everett	Snohomish County (Paine Field)	1/4386	VOR or GPS-B, Orig-A

[FR Doc. 01-12485 Filed 5-16-01; 8:45 am]  
 BILLING CODE 4910-13-M

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 97**

[Docket No. 30247; Amdt. No. 2050]

**Standard Instrument Approach Procedures; Miscellaneous Amendments**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference-approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

*For Examination—*

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
2. The FAA Regional Office of the region in which the affected airport is located; or
3. The Flight Inspection Area Office which originated the SIAP.

*For Purchase—*

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

**FOR FURTHER INFORMATION CONTACT:** Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169

**ADDRESSES:** (Mail P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

**The Rule**

This amendment to part 97 is effective upon publication of each separate SIAP