

lights. The Deputy Assistant Judge Advocate General (Admiralty and Maritime Law) of the Navy has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR Parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

List of Subjects in 32 CFR Part 706

Marine safety, Navigation (water), and Vessels.

Accordingly, 32 CFR Part 706 is amended as follows:

PART 706—[AMENDED]

1. The authority citation for 32 CFR Part 706 continues to read as follows:

Authority: 33 U.S.C. 1605.

2. Table Four, Paragraph 16 of § 706.2 is amended by revising the following entry for USS DONALD COOK:

§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.

* * * * *

Vessel	Number	Obstruction angle relative to ship's headings
USS DONALD COOK.	DDG 75	108.78 thru 112.50°
		* * * * *
		3. Table Five of § 706.2 is amended by revising the following entry for USS DONALD COOK:
		§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.
		* * * * *

TABLE FIVE

Vessel	No.	Masthead lights not over all other lights and obstructions. annex I, sec. 2(f)	Forward masthead light not in forward quarter of ship. annex I, sec. 3(a)	After masthead light less than 1/2 ship's length aft of forward masthead light. annex I, sec. 3(a)	Percentage horizontal separation attained
USS DONALD COOK	DDG 75	*	X	X	X 14.8
		*	*	*	*

Dated: February 13, 2002.

Richard T. Evans,
Captain, JAGC, U.S. Navy, Deputy Assistant Judge Advocate, General (Admiralty and Maritime Law).

Dated: April 9, 2002.

T.J. Welsh,
LCDR, JAGC, USN, Federal Register Liaison Officer.
[FR Doc. 02-9168 Filed 4-15-02; 8:45 am]
BILLING CODE 3810-FF-P

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Part 117

[CGD01-02-042]

Drawbridge Operation Regulations: Taunton River, MA

AGENCY: Coast Guard, DOT.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, First Coast Guard District, has issued a temporary deviation from the drawbridge operation regulations for the Brightman Street Bridge, mile 1.8, across the Taunton River between Somerset and Fall River, Massachusetts. This deviation from the

regulations, effective from 9 p.m. on April 12, 2002 through 4 p.m. on April 26, 2002, allows the bridge to remain in the closed position for vessel traffic to facilitate scheduled maintenance at the bridge.

DATES: This deviation is effective from April 12, 2002 through April 26, 2002.

FOR FURTHER INFORMATION CONTACT: John W. McDonald, Project Officer, First Coast Guard District, at (617) 223-8364.

SUPPLEMENTARY INFORMATION: The bridge owner, Massachusetts Highway Department, requested a temporary deviation from the drawbridge operating regulations on February 11, 2002, to facilitate necessary structural repairs at the bridge, replacement of the main floor beam, from 9 p.m. on April 5, 2002 through 4 p.m. on April 19, 2002.

The Coast Guard published a temporary deviation (CGD01-02-035) on March 27, 2002, to facilitate the above scheduled bridge maintenance. The Coast Guard received a revised request from the owner of the bridge changing the effective period for this scheduled bridge maintenance to 9 p.m. on April 12, 2002 through 4 p.m. on April 26, 2002, as a result of a late response from an upstream facility expecting a ship delivery that would be

in conflict with the original effective period.

As a result of the above information, this deviation to the operating regulations, cancels the temporary deviation (CGD01-02-035) published on March 27, 2002, and allows the Brightman Street Bridge to remain in the closed position for vessel traffic from 9 p.m. on April 12, 2002 through 4 p.m. on April 26, 2002.

This deviation from the operating regulations is authorized under 33 CFR 117.35, and will be performed with all due speed in order to return the bridge to normal operation as soon as possible.

Dated: April 3, 2002.

G.N. Naccara,
Rear Admiral, U.S. Coast Guard, Commander, First Coast Guard District.
[FR Doc. 02-9132 Filed 4-15-02; 8:45 am]
BILLING CODE 4910-15-U