

location where the requirements of this AD can be done.

Continuous Airworthiness Maintenance Program

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record keeping requirement of § 121.369 (c) of the Federal Aviation Regulations (14 CFR 121.369 (c)) of this chapter must maintain records of the mandatory inspections that result from revising the Time Limits section of the Instructions for Continuous Airworthiness (ICA) and the air carrier's continuous airworthiness program. Alternately, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369 (c) of the Federal Aviation Regulations (14 CFR 121.369 (c)); however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380 (a) (2) (vi) of the Federal Aviation Regulations (14 CFR 121.380 (a) (2) (vi)). All other operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

Note 3: The requirements of this AD have been met when the engine manual changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the engine manuals.

Effective Date

(f) This amendment becomes effective on February 24, 2003.

Issued in Burlington, Massachusetts, on August 21, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-21832 Filed 8-27-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 02-AAL-1]

Revision of Class E Airspace; Cordova, AK; Correction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects an error on one of the bearings listed in the

revised Class E airspace description at Cordova, AK, in the final rule and the coordinates for the exclusion line that were published in the **Federal Register** on July 25, 2002 (67 FR 48545), Airspace Docket 02-AAL-1.

EFFECTIVE DATE: 0901 UTC, October 3, 2002.

FOR FURTHER INFORMATION CONTACT:

Derril Bergt, Operations Branch, AAL-538, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587; telephone number (907) 271-2796; fax: (907) 271-2850; e-mail: *Derril.ctr.Bergt@faa.gov*. Internet address: *http://www.alaska.faa.gov/at* or at address *http://162.58.28.41/at*.

SUPPLEMENTARY INFORMATION:

History

Federal Register Document 02-18620, Airspace Docket 02-AAL-1, published on July 25, 2002 (67 FR 48545) revised the Class E airspace area at Cordova, AK. The verbiage “* * * 060° bearing from the Glacier River NDB extending from the 4.1-mile radius to 6 miles northeast * * *” should read “* * * 114° bearing from the Glacier River NDB extending from the 4.1-mile radius to 6 miles southeast * * *” and the verbiage “* * * from lat. 60° 31’ 00” N, long. 145° 20’ 00” W; to lat. 60° 31’ 03” N, long. 145° 20’ 59” W.” should read “* * * from lat. 60° 31’ 03” N, long. 145° 20’ 59” W; to lat. 60° 32’ 45” N, long. 145° 33’ 43” W.” This action corrects these errors.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the Class E description listed for the Cordova, Merle K. (Mudhole) Airport as published in the **Federal Register** on July 25, 2002 (67 FR 48545), (**Federal Register** Document 02-18620), is corrected as follows:

§ 71.1 [Corrected]

1. On page 48546, in column one, the Class E airspace description for Cordova, AK, is corrected to read as follows:

* * * * *

AAL AK E2 Cordova, AK [Corrected]

Cordova, Merle K. (MUDHOLE) Smith Airport, AK
(Lat. 60° 29’ 31” N., long. 145° 28’ 39” W.)
Glacier River NDB
(Lat. 60° 29’ 56” N., long. 145° 28’ 28” W.)

Within a 4.1 mile radius of the Merle K. (Mudhole) Smith airport and within 2.1 miles each side of the 222° bearing from the Glacier River NDB extending from the 4.1 mile radius to 10 miles southwest of the airport and within 2 miles either side of the

114° bearing from the Glacier River NDB extending from the 4.1-mile radius to 6 miles southeast of the airport and within 2.2 miles each side of the 142° bearing from the NDB extending from the 4.1-mile radius to 10.4 miles southeast of the airport, excluding that airspace north of a line from lat. 60° 31’ 03” N, long. 145° 20’ 59” W; to lat. 60° 32’ 45” N, long. 145° 33’ 43” W.

* * * * *

Issued in Anchorage, AK, on August 5, 2002.

Stephen P. Creamer,

Assistant Manager, Air Traffic Division, Alaskan Region.

[FR Doc. 02-21134 Filed 8-27-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30325; Amdt. No. 3019]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provided safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective August 28, 2002. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 28, 2002.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The Flight Inspection Area Office which originated the SIAP; or,

4. The Office of Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

For Purchase—

Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—

Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125); telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form

documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC on August 16, 2002.

James J. Ballough,

Director, Flight Standards Service.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

1. The authority citation for part 97 is revised to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120, 44701; and 14 CFR 11.49(b)(2).

§§ 97.23, 97.25, 97.27, 97.29, 97.31, 97.33, and 97.35 [Amended]

2. Part 97 is amended as follows:

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, identified as follows:

* * * *Effective October 3, 2002*

Batesville, AR, Batesville Regional, SDF RWY 7, Amdt 8A, CANCELLED
Norton, KS, Norton Muni, NDB RWY 16, Orig Springhill, LA, Springhill, NDB RWY 35, Orig, CANCELLED
Springhill, LA, Springhill, NDB RWY 36, Orig
St. Louis, MO, Lambert—St. Louis Intl, VOR/DME RWY 17, ORIG—A, CANCELLED
Fremont, NE, Fremont Muni, VOR RWY 13, Amdt 1
Fremont, NE, Fremont Muni, NDB RWY 13, Amdt 3
Grant, NE, Grant Muni, VOR/DME RWY 15, ORIG
Manchester, NH, Manchester, RNAV (GPS) RWY 6, Orig
Manchester, NH, Manchester, RNAV (GPS) RWY 24, Orig
Manchester, NH, Manchester, GPS RWY 6, Orig-A, CANCELLED
Aguadilla, PR, Rafael Hernandez, VOR RWY 8, Amdt 6
Aguadilla, PR, Rafael Hernandez, VOR/DME RWY 8, Amdt 2
Aguadilla, PR, Rafael Hernandez, RNAV (GPS) RWY 8, Orig
Aguadilla, PR, Rafael Hernandez, GPS RWY 8, Orig, CANCELLED
Andrews, SC, Robert F. Swinne, NDB RWY 36, Orig
Baytown, TX, Baytown, VOR RWY 14, Amdt 1, CANCELLED
Baytown, TX, Baytown, GPS RWY 14, Orig, CANCELLED
Baytown, TX, Baytown, GPS RWY 32, Orig, CANCELLED
Baytown, TX, Baytown, VOR RWY 32, Amdt 1, CANCELLED

Gordonsville, VA, Gordonsville Muni. NDB OR GPS RWY 23, Amdt 1, CANCELLED
 Orange, VA, Orange County, NDB RWY 7, Amdt 1A, CANCELLED
 Tomahawk, WI, Tomahawk Regional, VOR/DME-A, Amdt 1
 Jackson, WY, Jackson Hole, ILS RWY 18, Amdt 8

* * * Effective November 28, 2002

Charleston, SC, Charleston AFB/Intl, VOR/DME OR TACAN RWY 3, Amdt 14
 Immokalee, FL, Immokalee, VOR OR GPS RWY 18, Amdt 5

Note: The FAA published the following procedure in transmittal letter 02-18 dated August 2, 2002 effective October 3, 2002 which is hereby rescinded:

Oakland, CA, Metropolitan Oakland Intl, VOR/DME RWY 29, Amdt 1

[FR Doc. 02-21819 Filed 8-27-02; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30326; Amdt. No. 3020]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective August 28, 2002. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 28, 2002

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

4. The Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

*For Purchase—*Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the

SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAMs for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these chart changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPS. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial