

**Applicability**

(c) This AD applies to Cessna Model 500, 501, 550, 551, S550, 560, 560XL, and 750

airplanes, certificated in any category; as identified in the service bulletins specified in Table 1 of this AD.

TABLE 1.—CESSNA SERVICE BULLETINS

Cessna Service Bulletin	Revision	Date	Cessna model
SB500–26–02 .....	1 .....	July 7, 2005 .....	500/501 airplanes.
SB500–26–02 .....	Original .....	April 1, 2005 .....	500/501 airplanes.
SB550–26–05 .....	Original .....	April 1, 2005 .....	550/551 airplanes.
SB560–26–01 .....	Original .....	April 1, 2005 .....	560 airplanes.
SB560XL–26–02 .....	1 .....	December 22, 2004 .....	560XL airplanes.
SB750–26–05 .....	Original .....	November 24, 2004 .....	750 airplanes.
SBS550–26–02 .....	Original .....	April 1, 2005 .....	S550 airplanes.

**Unsafe Condition**

(d) This AD results from a report of miswired fire extinguishing bottles. We are issuing this AD to ensure that the fire extinguishing bottles are activated in the event of an engine or auxiliary power unit (APU) fire, and that flammable fluids are not supplied during a fire, which could result in an unextinguished fire in the nacelle or APU.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Requirements of AD 2006–04–10****Installation**

(f) For Model 500, 550, S550, 560, 560XL, and 750 airplanes: Within 100 flight hours or 60 days after March 24, 2006 (the effective date of AD 2006–04–10), whichever occurs first, install identification sleeves on the wires for the positive and negative terminal studs of the applicable fire extinguishing bottles identified in paragraphs (f)(1), (f)(2), and (f)(3) of this AD; re-connect the wires to the correct studs; test the connection; and re-connect the wires again as applicable until the connection tests correctly. Do all actions in accordance with the Accomplishment Instructions of the applicable service bulletin identified in Table 1 of this AD; except that, for Model 500 airplanes, Cessna Service Bulletin SB500–26–02, Revision 1, dated July 7, 2005 may be used. After the effective date of this AD, only Cessna Service Bulletin SB500–26–02, Revision 1, may be used to accomplish the requirements of this paragraph for Model 500 airplanes.

(1) For Cessna Model 500, 550, S550, and 560 airplanes: The engine fire extinguishing bottles.

(2) For Cessna Model 560XL airplanes: The engine and the APU fire extinguishing bottles.

(3) For Cessna Model 750 airplanes: The APU fire extinguishing bottle.

**Actions Accomplished in Accordance With Earlier Revision of Service Bulletin**

(g) For Model 560XL airplanes: Actions done before March 24, 2006, in accordance with the Accomplishment Instructions of Cessna Service Bulletin SB560XL–26–02, dated November 22, 2004, are acceptable for compliance with the corresponding actions in this AD.

**New Requirements of This AD****Actions for Additional Airplane Models**

(h) For Model 501 and 551 airplanes: Within 100 flight hours or 60 days after the effective date of this AD, whichever occurs first, do the actions required by paragraph (f) of this AD for the engine fire extinguishing bottles in accordance with Cessna Service Bulletin SB500–26–02, Revision 1, dated July 7, 2005, or Cessna Service Bulletin SB550–26–05, dated April 1, 2005; as applicable.

**Verification of Actions Accomplished Using Original Issue of Service Bulletin**

(i) For Model 500 airplanes on which the actions specified in Cessna Service Bulletin SB500–26–02, dated April 1, 2005, have been done before the effective date of this AD: Within 100 flight hours or 60 days after the effective date of this AD, whichever occurs first, verify that wiring changes previously done in accordance with Cessna Service Bulletin SB500–26–02, dated April 1, 2005, conform to the changes described in Cessna Service Bulletin SB500–26–02, Revision 1, dated July 7, 2005; and, if any non-conforming wiring changes are discovered, before further flight, correct the wiring changes as applicable to conform to the changes described in Cessna Service Bulletin SB500–26–02, Revision 1, dated July 7, 2005.

**No Reporting Requirement**

(j) Although the Accomplishment Instructions of the service bulletins identified in Table 1 of this AD describe procedures for submitting a maintenance transaction report to the manufacturer, this AD does not require that action.

**Parts Installation**

(k) At the applicable time specified in paragraph (k)(1) or (k)(2) of this AD, no person may install on any airplane a fire extinguishing bottle unless identification sleeves on the wires for the positive and negative terminal studs have been installed in accordance with paragraph (f) or (h) of this AD, as applicable.

(1) For Model 500, 550, S550, 560, 560XL, and 750 airplanes: After March 24, 2006.

(2) For Model 501 and 551 airplanes: After the effective date of this AD.

**Alternative Methods of Compliance (AMOCs)**

(l)(1) The Manager, Wichita Aircraft Certification Office, FAA, has the authority to

approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on February 8, 2007.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–2628 Filed 2–14–07; 8:45 am]

BILLING CODE 4910–13–P

**DEPARTMENT OF THE INTERIOR****National Indian Gaming Commission****25 CFR Parts 502 and 546****Class II Definitions and Game Classification Standards; Withdrawal**

**AGENCY:** National Indian Gaming Commission.

**ACTION:** Notice of withdrawal of proposed regulations.

**SUMMARY:** The purpose of this document is to notify the public that the National Indian Gaming Commission is withdrawing the proposed regulations published in the **Federal Register** on May 25, 2006 (71 FR 30232, 71 FR 30238).

**FOR FURTHER INFORMATION CONTACT:** John Hay at 202/632–7003; fax 202/632–7066 (these are not toll-free numbers).

**SUPPLEMENTARY INFORMATION:** Congress established the National Indian Gaming Commission (NIGC or Commission) under the Indian Gaming Regulatory Act of 1988 (25 U.S.C. 2701 *et seq.*) (IGRA) to regulate gaming on Indian lands. On May 25, 2006, proposed Class II definitions and game classification standards were published in the **Federal Register** (71 FR 30232, 71 FR 30238). After receiving extensive comment, and

after many consultations with tribal governments and tribal regulators, the Commission anticipates significant revisions to any proposed rule. As such, the Commission has decided to withdraw the current proposed rule and may publish a new proposed rule at a later date.

Dated: February 9, 2007.

**Philip N. Hogen,**  
Chairman, National Indian Gaming  
Commission.

[FR Doc. E7-2621 Filed 2-14-07; 8:45 am]

BILLING CODE 7565-01-P

## DEPARTMENT OF THE INTERIOR

### National Indian Gaming Commission

#### 25 CFR Part 547

#### Technical Standards for Electronic, Computer, or Other Technologic Aids Used in the Play of Class II Games; Withdrawal

**AGENCY:** National Indian Gaming Commission, Interior.

**ACTION:** Notice of withdrawal of proposed rule.

**SUMMARY:** This is to notify the public that the National Indian Gaming Commission is withdrawing the proposed rule published in the **Federal Register** on August 11, 2006. (71 FR 46335.)

**FOR FURTHER INFORMATION CONTACT:** Michael Gross at 202/632-7003; fax 202/632-7066 (these are not toll-free numbers).

**SUPPLEMENTARY INFORMATION:** Congress established the National Indian Gaming Commission (Commission) under the Indian Gaming Regulatory Act of 1988, 25 U.S.C. 2701 *et seq.*, to regulate gaming on Indian lands. On August 11, 2006, the Commission published a proposed rule, "Technical Standards for Electronic, Computer, or other Technologic Aids Used in the Play of Class II Games." (71 FR 46335). After receiving extensive comment, and after many consultations with tribal governments and tribal regulators, the Commission anticipates significant revisions to any proposed rule. As such, the Commission has decided to withdraw the current proposed rule and may publish a new proposed rule at a later date.

Dated: February 9, 2007.

**Philip N. Hogen,**  
Chairman, National Indian Gaming  
Commission.

[FR Doc. E7-2623 Filed 2-14-07; 8:45 am]

BILLING CODE 7565-01-P

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Parts 1, 20, 25, 31, 53, 54, and 56

[REG-103038-05]

RIN 1545-BE24

#### AJCA Modifications to the Section 6011 Regulations

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of public hearing on proposed rulemaking.

**SUMMARY:** This document provides notice of public hearing on proposed rulemaking relating to the disclosure of reportable transactions under section 6011.

**DATES:** The public hearing is being held on Tuesday, March 20, 2007, at 10 a.m. The IRS must receive outlines of the topics to be discussed at the public hearing by March 6, 2007.

**ADDRESSES:** The public hearing is being held in the IRS Auditorium, Internal Revenue Service Building, 1111 Constitution Avenue, NW., Washington, DC 20224. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present photo identification to enter the building.

Mail outlines to CC:PA:LPD:PR (REG-103038-05), room 5205, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG-103038-05), Couriers Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC or sent electronically via the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov) (IRS-REG-103038-05).

**FOR FURTHER INFORMATION CONTACT:** Concerning submissions of comments, the hearing and/or to be placed on the building access list to attend the hearing Kelly Banks at (202) 622-7180 (not a toll-free number).

**SUPPLEMENTARY INFORMATION:** The subject of the public hearing is the notice of proposed rulemaking (REG-103038-05) that was published in the **Federal Register** on Thursday, November 2, 2006 (71 FR 64488). The rules of 26 CFR 601.601(a)(3) apply to the hearing.

A period of 10 minutes is allotted to each person for presenting oral

comments. After the deadline has passed, persons who have submitted written comments and wish to present oral comments at the hearing must submit an outline of the topics to be discussed and the amount of time to be devoted to each topic (a signed original and eight copies) by March 6, 2007.

The IRS will prepare an agenda containing the schedule of speakers. Copies of the agenda will be made available free of charge at the hearing. Because of access restrictions, the IRS will not admit visitors beyond the immediate entrance area more than 30 minutes before the hearing starts. For information about having your name placed on the building access list to attend the hearing, see the **FOR FURTHER INFORMATION CONTACT** section of this document.

**LaNita Van Dyke,**

Branch Chief, Publications and Regulations  
Branch, Legal Processing Division, Associate  
Chief Counsel, (Procedure and  
Administration).

[FR Doc. E7-2590 Filed 2-14-07; 8:45 am]

BILLING CODE 4830-01-P

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Parts, 20, 25, 31, 53, 54, and 56

[REG-103039-05]

RIN 1545-BE26

#### AJCA Modifications to the Section 6111 Regulations

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of public hearing on proposed rulemaking.

**SUMMARY:** This document provides notice of public hearing on proposed rulemaking relating to the disclosure of reportable transactions by material advisors under section 6111.

**DATES:** The public hearing is being held on Tuesday, March 20, 2007, at 10 a.m. The IRS must receive outlines of the topics to be discussed at the public hearing by March 6, 2007.

**ADDRESSES:** The public hearing is being held in the IRS Auditorium, Internal Revenue Service Building, 1111 Constitution Avenue, NW., Washington, DC 20224. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present photo identification to enter the building.

Mail outlines to CC:PA:LPD:PR (REG-103039-05), room 5205, Internal Revenue Service, POB 7604, Ben