

Corrections

Federal Register

Vol. 71, No. 34

Wednesday, February 21, 2007

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

Wednesday, December 27, 2006, make the following corrections:

§ 86.244–94 [Corrected]

1. On page 77926, in the third column, in § 86.244–94, in the second line from the bottom of the section, “CH4” should read “CH₄”.

§ 600.114–08 [Corrected]

2. On page 77941, in § 600.114–08(c)(1)(ii)(B) the equation is corrected to read as follows:

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Parts 86 and 600

[EPA-HP-OAR-2005-0169; FRL-8257-5]

RIN 2060-AN14

Fuel Economy Labeling of Motor Vehicles: Revisions to Improve Calculation of Fuel Economy Estimates

Correction

In rule document 06–9749 beginning on page 77872 in the issue of

$$(B) \text{ Running FC} = 1.007 \times \left[\frac{0.79}{\text{US06 Highway FE}} - \frac{0.21}{\text{HFET FE}} \right] + 0.133 \times 0.377 \times \left[\frac{1}{\text{SC03 FE}} - \left(\frac{0.61}{\text{Bag } 3_{75} \text{ FE}} + \frac{0.39}{\text{Bag } 4_{75} \text{ FE}} \right) \right]$$

§ 600.315–08 [Corrected]

3. On page 77954, in the first column, in § 600.315–08(g)(1)(i), in the first line, “W4–;” should read “W4–”.

4. On the same page, in the same column, in § 600.315–08(g)(1)(ii), in the first line, “H201–;” should read “H201–”.

5. On the same page, in the same column, in § 600.315–08(g)(1)(iii), in the first line, “L205–;” should read “L205–”.

6. On the same page, in the same column, in § 600.315–08(g)(2)(i)(B), in the first line, “L211–;” should read “L211–”.

7. On the same page, in the same column, in § 600.315–08(g)(2)(ii), in the first line, “W4–;” should read “W4–”.

8. On the same page, in the same column, in § 600.315–08(g)(2)(iii), in the first line, “H198–;” should read “H198–”.

[FR Doc. C6–9749 Filed 2–20–07; 8:45 am]

BILLING CODE 1505–01–D