

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Agusta S.p.A.: Docket No. FAA-2009-0168; Directorate Identifier 2007-SW-33-AD.

Comments Due Date

(a) We must receive comments by April 8, 2009.

Other Affected ADs

(b) None.

Applicability

(c) This AD applies to Model AB139 helicopters, serial number (S/N) 31005 through 31054, except S/N 31007, and AW139 helicopters, S/N 31055 through 31067, S/N 31070, and S/N 31071, certificated in any category.

Reason

(d) The mandatory continuing airworthiness information (MCAI) states that during the installation of a fire extinguisher bottle, part number 3G2620V00131, on a helicopter during manufacture, it was found that the electrical receptacle/connectors on the bottle which commands the firing of the extinguishing agent were swapped between engines No. 1 and No. 2. This condition could affect helicopters already in service and fire extinguisher bottles of the same part number in stock as spare parts. If not

corrected, an improperly wired fire extinguishing bottle might cause the extinguishing agent to be discharged toward the unselected engine when the system is activated, rather than toward the engine with the fire. The proposed AD would require determining if each engine has the proper outlet end on the electrical receptacle/connector that attaches the firing cartridge to the fire extinguisher bottle, and if not, replacing the fire extinguisher bottle. The proposed AD is intended to prevent the fire extinguishing agent from not discharging toward the engine with the fire, which could result in loss of the helicopter due to an engine fire.

Actions and Compliance

(e) Within 100 hours time-in-service (TIS) or 3 months, whichever occurs first, unless already done, do the following actions.

(1) Determine whether the fire extinguishing bottle (bottle) for engines No. 1 and No. 2 have the proper outlet end on the electrical receptacle/connector, which attaches the firing cartridge to the bottle, by following steps 4. and 5. of the Compliance Instructions in Agusta Bollettino Tecnico No. 139-085, dated May 18, 2007 (BT).

(2) If a bottle has an electrical receptacle/connector for the firing cartridge with an improper outlet end, before further flight, replace the bottle with a bottle that has an electrical receptacle/connector with a proper outlet end in accordance with step 6. of the Compliance Instructions in the BT.

Differences Between the FAA AD and the MCAI

(f) This AD uses the term "hours time-in-service" rather than "flight hours."

Other FAA Information

(g) Alternative Methods of Compliance (AMOCs): The Manager, Safety Management Group, Rotorcraft Directorate, FAA, ATTN: John Strasburger, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Policy Group, 2601 Meacham Blvd., Fort Worth, Texas 76193-0111; telephone (817) 222-5167; fax (817) 222-5961, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) MCAI Ente Nazionale Per L'Aviazione Civile Airworthiness Directive No. 2007-227, dated June 18, 2007, contains related information.

Air Transport Association of America (ATA) Tracking Code

(i) ATA Code 2621: Fire Bottle, Fixed.

Issued in Fort Worth, Texas, on February 19, 2009.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E9-4943 Filed 3-6-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0127; Airspace Docket No. 09-AGL-4]

Proposed Amendment of Class E Airspace; Cleveland, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Cleveland, OH. Additional controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Lorain County Regional Airport, Lorain, OH. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) aircraft operations at Lorain County Regional Airport.

DATES: 0901 UTC. Comments must be received on or before April 23, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0127/Airspace Docket No. 09-AGL-4, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76193-0530; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments

are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2009-0127/Airspace Docket No. 09-AGL-4." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by adding additional Class E airspace in the Cleveland, OH area for SIAPs operations at Lorain County Regional Airport, Lorain, OH. The area would be depicted on appropriate aeronautical charts.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9S, dated October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It,

therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would add additional controlled airspace in the Cleveland, OH area.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9S, Airspace Designations and Reporting Points, dated October 3, 2008, and effective October 31, 2008, is amended as follows:

Paragraph 6005 Class E Airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AGL OH E5 Cleveland, OH [Amended]

That airspace extending upward from 700 feet above the surface bounded by a line beginning at lat. 41°25'00" N., long. 82°23'00" W., to lat. 41°56'00" N., long. 81°22'00" W., to lat. 41°48'00" N., long. 81°02'00" W., to lat. 41°32'00" N., long. 81°03'00" W., to lat. 41°11'00" N., long. 81°48'00" W., to lat. 41°11'00" N., long. 82°21'00" W., to lat. 41°14'39" N., long. 82°21'44" W., to lat. 41°18'06" N., long. 82°23'52" W., to lat. 41°18'42" N., long. 82°22'07" W., thence to the point of beginning.

* * * * *

Issued in Fort Worth, TX, on February 26, 2009.

Walter L. Tweedy.

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. E9-4895 Filed 3-6-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0115; Airspace Docket No. 09-AGL-3]

Proposed Amendment of Class E Airspace; Mount Sterling, IL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Mount Sterling, IL. Additional controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Mount Sterling Municipal Airport, Mount Sterling, IL. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) aircraft operations at Mount Sterling Municipal Airport.

DATES: 0901 UTC. Comments must be received on or before April 23, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0115/Airspace Docket No. 09-AGL-3, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through