

respect to compliance with most FMVSS.

WETL submitted information with its petition intended to demonstrate that non-U.S. certified 2006 Porsche Cayenne MPVs manufactured prior to September 1, 2006, as originally manufactured, conform to many FMVSS in the same manner as their U.S. certified counterparts, or are capable of being readily altered to conform to those standards.

Specifically, the petitioner claims that non-U.S. certified 2006 Porsche Cayenne MPVs manufactured prior to September 1, 2006, are identical to their U.S.-certified counterparts with respect to compliance with Standard Nos. 102 *Transmission Shift Lever Sequence, Starter Interlock, and Transmission Braking Effect*, 103 *Windshield Defrosting and Defogging Systems*, 104 *Windshield Wiping and Washing Systems*, 106 *Brake Hoses*, 113 *Hood Latch System*, 116 *Motor Vehicle Brake Fluids*, 118 *Power-Operated Window, Partition, and Roof Panel Systems*, 119 *New Pneumatic Tires for Vehicles Other than Passenger Cars*, 120 *Tire Selection and Rims for Motor Vehicles Other than Passenger Cars*, 124 *Accelerator Control Systems*, 135 *Light Vehicle Brake Systems*, 201 *Occupant Protection in Interior Impact*, 202 *Head Restraints*, 204 *Steering Control Rearward Displacement*, 205 *Glazing Materials*, 206 *Door Locks and Door Retention Components*, 207 *Seating Systems*, 209 *Seat Belt Assemblies*, 210 *Seat Belt Assembly Anchorages*, 212 *Windshield Mounting*, 214 *Side Impact Protection*, 216 *Roof Crush Resistance*, 219 *Windshield Zone Intrusion*, 225 *Child Restraint Anchorage Systems*, and 302 *Flammability of Interior Materials*.

Petitioner also contends that the vehicle is capable of being readily altered to meet the following standards, in the manner indicated:

Standard No. 101 *Controls and Displays*: Inscription of the word "brake" on the instrument cluster in place of the international ECE warning symbol and installation of a U.S.-model speedometer, or modification of the existing speedometer to conform with the requirements of this standard.

Standard No. 108 *Lamps, Reflective Devices and Associated Equipment*: Installation of U.S.-model headlamps and tail lamps to meet the requirements of this standard.

Standard No. 111 *Rearview Mirrors*: Installation of a U.S.-model passenger side rearview mirror, or inscription of the required warning statement on the face of that mirror on all vehicles not already so equipped.

Standard No. 114 *Theft Protection*: Installation of a supplemental key warning buzzer, or installation of U.S.-version software on all vehicles not already so equipped.

Standard No. 208 *Occupant Crash Protection*: Installation of a seat belt warning system that meets the requirements of this standard.

The petitioner states that the crash protection system used in these vehicles consists of dual front airbags, knee bolsters, and combination lap and shoulder belts at the front outboard seating positions.

Standard No. 301 *Fuel System Integrity*: Inspection of all vehicles and replacement of any non-U.S.-model fuel system components with U.S.-model components.

The petitioner additionally states that a vehicle identification plate must be affixed to the vehicles near the left windshield post to meet the requirements of 49 CFR Part 565.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above addresses both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: May 27, 2009.

Claude H. Harris,

Director, Office of Vehicle Safety Compliance.
[FR Doc. E9-12842 Filed 6-2-09; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

May 27, 2009.

The Department of the Treasury will submit the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13 on or after the date of publication of this notice. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 11000, 1750

Pennsylvania Avenue, NW., Washington, DC 20220.

DATES: Written comments should be received on or before July 6, 2009 to be assured of consideration.

Financial Management Service (FMS)

OMB Number: 1510-0037.

Type of Review: Extension.

Form: TFS 5135.

Title: Voucher for Payment of Awards.

Description: Awards certified to Treasury are paid annually as funds are received from foreign governments. Vouchers are mailed to award holders showing payments due. Award holders sign vouchers certifying that he/she is entitled to payment.

Respondents: Individuals or households.

Estimated Total Burden Hours: 700 hours.

OMB Number: 1510-0043.

Type of Review: Extension.

Form: FMS-133, FMS-135.

Title: Notice of Reclamation and Debit Request for Recurring Benefit Payments.

Description: A program agency authorizes Treasury to recover payments that have been issued after the death of the beneficiary. FMS Form 133 is used to notify the FI. If the FI does not respond to the 133, a debit request (Form 135) is sent to the FRB.

Respondents: Businesses or other for-profit institutions.

Estimated Total Burden Hours: 79,335 hours.

OMB Number: 1510-0045.

Type of Review: Extension.

Form: FMS-150-1, FMS-150-2.

Title: Trace Request for EFT Payments.

Description: Used to notify the FI that a beneficiary has claimed non-receipt of credit for a payment. The form is designed to help the FI locate any problem and to keep the beneficiary informed of any action taken.

Respondents: Businesses or other for-profit institutions.

Estimated Total Burden Hours: 17,971 hours.

Clearance Officer: Wesley Powe, (202) 874-7662, Financial Management Service, Room 135, 3700 East West Highway, Hyattsville, MD 20782.

OMB Reviewer: Shagufta Ahmed, (202) 395-7873, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Celina Elphage,

Treasury PRA Clearance Officer.

[FR Doc. E9-12957 Filed 6-2-09; 8:45 am]

BILLING CODE 4810-35-P