

Positioning System (GPS) standard instrument approach procedures at Bryce Canyon Airport. This will improve the safety of Instrument Flight Rules (IFR) aircraft executing RNAV GPS standard instrument approach procedures at Bryce Canyon Airport.

DATES: Effective date, 0901 UTC, June 30, 2011. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:

History

On December 9, 2010, the FAA published in the **Federal Register** a notice of proposed rulemaking to establish additional controlled airspace at Bryce Canyon, UT (75 FR 76650). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. The FAA received two comments. One commenter suggested adding airspace to the eastern boundary of the 1,200 foot AGL airspace description. The FAA found merit in this comment, and will incorporate this change in the final rule. The second commenter was concerned with the possible impact of noise on the Bryce Canyon National Park. This rule will only modify the existing airspace to the extent necessary to increase flight safety. The FAA does not believe this will create any change in the intensity, frequency of flight activity, or existing patterns of noise generation. With the exception of editorial changes and the changes described above, this rule is the same as that proposed in the NPRM.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9U dated August 18, 2010, and effective September 15, 2010, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in that Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by amending the Class E airspace for the Bryce Canyon, UT area, adding additional controlled airspace extending upward from 700 feet above the surface to accommodate IFR aircraft executing RNAV (GPS) standard instrument

approach procedures at Bryce Canyon Airport. This action is necessary for the safety and management of IFR operations at the airport.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, section 106 discusses the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes additional controlled airspace at Bryce Canyon Airport, Bryce Canyon, UT.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

- 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E. O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

- 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9U,

Airspace Designations and Reporting Points, dated August 18, 2010, and effective September 15, 2010 is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM UT E5 Bryce Canyon, UT [Modified]

Bryce Canyon Airport, UT
(Lat. 37°42'23" N., long. 112°08'45" W.)

That airspace extending upward from 700 feet above the surface within 8 miles each side of the 047° and 227° bearing from the airport, extending 18 miles northeast and 15.9 miles southwest of the airport. That airspace extending upward from 1,200 feet above the surface bounded by a line beginning at lat. 38°21'00" N., long. 112°34'00" W.; to lat. 38°21'00" N., long. 112°24'00" W.; to lat. 38°12'00" N., long. 112°15'00" W.; to lat. 38°20'00" N., long. 111°56'00" W.; to lat. 38°18'00" N., long. 111°41'00" W.; to lat. 38°00'00" N., long. 111°34'00" W.; to lat. 37°45'00" N., long. 111°02'00" W.; to lat. 37°17'00" N., long. 111°18'00" W.; to lat. 37°19'00" N., long. 111°48'00" W.; to lat. 37°22'00" N., long. 112°14'00" W.; to lat. 37°13'00" N., long. 112°33'00" W.; to lat. 37°14'00" N., long. 112°39'00" W.; to lat. 37°29'00" N., long. 112°42'00" W.; to lat. 37°41'00" N., long. 112°53'00" W.; thence to point of origin.

Issued in Seattle, Washington, on March 10, 2011.

John Warner,
Manager, Operations Support Group, Western Service Center.

[FR Doc. 2011-6350 Filed 3-17-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG-2011-0079]

Drawbridge Operation Regulation; Townsend Inlet, Avalon, NJ

AGENCY: Coast Guard, DHS.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, Fifth Coast Guard District, has issued a temporary deviation from the regulations governing the operation of the Townsends Inlet Bridge across, mile 0.3, at Avalon, NJ. The deviation is necessary to facilitate the cleaning and painting of the structure. This deviation allows the bridge to remain in the closed position for the deviation period.

DATES: This deviation is effective from 5 a.m. on March 1, 2011 to 5 p.m. on April 30, 2011.

ADDRESSES: Documents mentioned in this preamble as being available in the docket are part of docket USCG–2011–0079 and are available online by going to <http://www.regulations.gov>, inserting USCG–2011–0079 in the “Keyword” box and then clicking “Search”. They are also available for inspection or copying at the Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or e-mail Mr. Terrance A. Knowles, Environmental Protection Specialist, Fifth District; Coast Guard; telephone 757–398–6587, e-mail Terrance.A.Knowles@uscg.mil. If you have questions on viewing the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202–366–9826.

SUPPLEMENTARY INFORMATION: The Cape May County Bridge Commission (CMCBC), who owns and operates this bascule drawbridge, has requested a temporary deviation from the current operating schedule to facilitate the cleaning and painting of the bridge structure. Under the regular operating schedule required by 33 CFR 117.757, the bridge opens on signal, except from 9:15 a.m. to 2:30 p.m. on the fourth Sunday in March of every year, the draw need not open for vessels. If the fourth Sunday falls on a religious holiday, the draw need not open from 9:15 a.m. to 2:30 p.m. on the third Sunday of March of every year. From 11 p.m. on December 24 until 11 p.m. on December 25, the draw need open only if at least two hours notice is given.

The Townsend Inlet Bridge, mile 0.3, in Avalon, NJ, has a vertical clearance in the closed position of 23 feet above mean high water. Vessels that can transit under the bridge without an opening may do so at any time. Under this temporary deviation, CMCBC will maintain the bridge in the closed position to vessels beginning at 5 a.m. on March 1, 2011 until and including 5 p.m. on April 30, 2011.

In 2010, during the months of March and April, the bridge has opened for vessels 62 and 45 times, respectively. The majority of the vessels for which the bridge opened were tugs and barges being used for beach replenishment.

The Coast Guard will inform users of the waterway through our Local and Broadcast Notices to Mariners of the closure periods for the bridge so that vessels can arrange their transits to

minimize any impact caused by the temporary deviation.

Vessels have two alternate routes by transiting either eight miles to the south through Hereford Inlet or eight miles to the north through Corson Inlet. The drawbridge will be able to open in the event of an emergency.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular operating schedule immediately at the end of the designated time period. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: March 7, 2011.

Waverly W. Gregory, Jr.,
Chief, Bridge Administration Branch, Fifth Coast Guard District.

[FR Doc. 2011–6338 Filed 3–17–11; 8:45 am]

BILLING CODE 9110–04–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG–2011–0150]

Drawbridge Operation Regulations; Annisquam River and Blynman Canal, Gloucester, MA

AGENCY: Coast Guard, DHS.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, First Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the SR127 Bridge at mile 0.0 across the Annisquam River and Blynman Canal. The deviation is necessary to facilitate a public event, the Yucan One-Mile Road Race, which will cross the SR127 Bridge. This deviation allows the bridge to remain in the closed position during the deviation period.

DATES: This deviation is effective from 8:45 a.m. through 10 a.m. on April 9, 2011.

ADDRESSES: Documents mentioned in this preamble as being available in the docket are part of docket USCG–2011–0150 and are available online at <http://www.regulations.gov>, inserting USCG–2011–0150 in the “Keyword” and then clicking “Search”. They are also available for inspection or copying at the Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or e-mail Mr. John McDonald, Project Officer, First Coast Guard District, john.w.mcdonald@uscg.mil, or telephone (617) 223–8364. If you have questions on viewing the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202–366–9826.

SUPPLEMENTARY INFORMATION: The SR127 Bridge, across the Annisquam River/Blynman Canal, mile 0.0, at Gloucester, Massachusetts, has a vertical clearance in the closed position of 7 feet at mean high water and 16 feet at mean low water. The drawbridge operation regulations are listed at 33 CFR 117.586.

The owner of the bridge, Massachusetts Department of Transportation, requested a temporary deviation from the regulations to facilitate the Yucan One-Mile Road Race which will pass across the SR127 Bridge.

Under this temporary deviation the SR127 Bridge may remain in the closed position between 8:45 a.m. and 10 a.m. on April 9, 2011. Vessels that can pass under the bridge in the closed position may do so at any time.

The Gloucester Harbor Master and the local marinas were notified and no objections were received.

In accordance with 33 CFR 117.35(e), the bridge must return to its regular operating schedule immediately at the end of the designated time period. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: March 8, 2011.

Gary Kasso,
Bridge Program Manager, First Coast Guard District.

[FR Doc. 2011–6342 Filed 3–17–11; 8:45 am]

BILLING CODE 9110–04–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG–2011–0149]

Drawbridge Operation Regulations; Bass River, Beverly, MA

AGENCY: Coast Guard, DHS.

ACTION: Notice of temporary deviation from regulations.

SUMMARY: The Commander, First Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the Hall Whitaker Bridge at mile 0.6 across the Bass River