

1. Is not a “significant regulatory action” under Executive Order 12866;  
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM (77 FR 20746, April 6, 2012), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2012-16-15 Bombardier, Inc.:** Amendment 39-17162. Docket No. FAA-2012-0328; Directorate Identifier 2011-NM-259-AD.

##### (a) Effective Date

This airworthiness directive (AD) becomes effective September 25, 2012.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category; serial numbers 7003 through 7067 inclusive, 7069 through 7990 inclusive, and 8000 through 8112 inclusive.

##### (d) Subject

Air Transport Association (ATA) of America Code 71: Powerplant.

##### (e) Reason

This AD was prompted by reports of jamming/malfunctioning of the left-hand engine thrust control mechanism. We are issuing this AD to prevent jamming/malfunctioning of the left-hand engine thrust control mechanism, which could lead to loss of control of the airplane.

##### (f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

##### (g) Actions

Within 36 months or 6,000 flight hours after the effective date of this AD, whichever occurs first: Modify the left-hand engine upper core-cowl, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-71-033, dated August 24, 2011.

##### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

##### (i) Related Information

Refer to MCAI Canadian Airworthiness Directive CF-2011-38, dated October 19, 2011; and Bombardier Service Bulletin 601R-71-033, dated August 24, 2011; for related information.

##### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-71-033, dated August 24, 2011.

(ii) Reserved.

(3) For Bombardier service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on August 9, 2012.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-20172 Filed 8-20-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### Food and Drug Administration

#### 21 CFR Parts 16 and 118

[Docket No. FDA-2011-D-0398]

#### Guidance for Industry: Questions and Answers Regarding the Final Rule, Prevention of Salmonella Enteritidis in Shell Eggs During Production, Storage, and Transportation; Availability

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Notice of availability.

**SUMMARY:** The Food and Drug Administration (FDA or we) is announcing the availability of a guidance entitled “Guidance for Industry: Questions and Answers Regarding the Final Rule, Prevention of Salmonella Enteritidis in Shell Eggs During Production, Storage, and Transportation.” The guidance contains questions we have received on the final rule since its publication and responses to those questions, and is intended to assist egg producers and other persons who are covered by the final rule.

**DATES:** Submit either electronic or written comments on Agency guidances at any time.

**ADDRESSES:** Submit written requests for single copies of the guidance to the Division of Plant and Dairy Food Safety/ Office of Food Safety, Center for Food Safety and Applied Nutrition (HFS-315), Food and Drug Administration, 5100 Paint Branch Pkwy., College Park, MD 20740. Send one self-addressed adhesive label to assist that office in processing your requests. See the **SUPPLEMENTARY INFORMATION** section for electronic access to the guidance.

Submit electronic comments on the guidance to <http://www.regulations.gov>. Submit written comments on the guidance to the Division of Dockets Management (HFA-305), Food and Drug Administration, 5630 Fishers Lane, Rm. 1061, Rockville, MD 20852.

**FOR FURTHER INFORMATION CONTACT:** Nancy Bufano, Center for Food Safety and Applied Nutrition (HFS-316), Food and Drug Administration, 5100 Paint Branch Pkwy., College Park, MD 20740, 240-402-1493.

**SUPPLEMENTARY INFORMATION:**

**I. Background**

In the **Federal Register** of July 9, 2009 (74 FR 33030), we issued a final rule requiring shell egg producers to implement measures to prevent *Salmonella* Enteritidis (SE) from contaminating eggs on the farm and from further growth during storage and transportation, and requiring these producers to maintain records concerning their compliance with the final rule and to register with FDA. This final rule became effective September 8, 2009. In the **Federal Register** of July 13, 2011 (76 FR 41157), we made available a draft guidance entitled "Questions and Answers Regarding the Final Rule, Prevention of *Salmonella* Enteritidis in Shell Eggs During Production, Storage, and Transportation" and gave interested parties an opportunity to submit comments by September 12, 2011. We have reviewed and evaluated these comments and have modified the guidance where appropriate.

This guidance is being issued consistent with FDA's good guidance practices regulation (21 CFR 10.115). The guidance represents our current thinking on how to interpret the requirements in the final rule, including questions and answers on compliance dates; coverage; definitions; SE prevention measures; sampling and testing for SE; registration; and compliance and enforcement. It does not create or confer any rights for or on any person and does not operate to bind

FDA or the public. An alternate approach may be used if such approach satisfies the requirements of the applicable statutes and regulations.

**II. Paperwork Reduction Act of 1995**

This guidance refers to previously approved collections of information found in FDA regulations. These collections of information are subject to review by the Office of Management and Budget (OMB) under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501-3520). The collections of information in 21 CFR 118.5, 118.6, 118.10, and 118.11 have been approved under OMB control number 0910-0660.

**III. Comments**

Interested persons may submit written comments regarding this document to the Division of Dockets Management (see **ADDRESSES**) or electronic comments to <http://www.regulations.gov>. It is only necessary to send one set of comments. Identify comments with the docket number found in brackets in the heading of this document. Received comments may be seen in the Division of Dockets Management between 9 a.m. and 4 p.m., Monday through Friday, and will be posted to the docket at <http://www.regulations.gov>.

**IV. Electronic Access**

Persons with access to the Internet may obtain the guidance at <http://www.fda.gov/FoodGuidances> or <http://www.regulations.gov>. Always access an FDA document using the FDA Web site listed previously to find the most current version of the guidance.

Dated: August 13, 2012.

**Leslie Kux,**

*Assistant Commissioner for Policy.*

[FR Doc. 2012-20383 Filed 8-20-12; 8:45 am]

**BILLING CODE 4160-01-P**

**DEPARTMENT OF THE TREASURY**

**Internal Revenue Service**

**26 CFR Part 1**

[TD 9597]

**RIN-1545-BF34**

**Deductions for Entertainment Use of Business Aircraft; Correction**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Correction to final regulations.

**SUMMARY:** This document corrects the final regulation (TD 9597) that was published in the **Federal Register** on Wednesday, August 1, 2012, (77 FR

45480), relating to the use of business aircraft for entertainment.

**DATES:** *Effective Date:* This correction is effective on August 21, 2012 and is applicable on August 1, 2012.

**FOR FURTHER INFORMATION CONTACT:** Michael Nixon (section 274), (202) 622-4930; or Lynne A. Camillo (section 61), (202) 622-6040 (not toll-free numbers).

**SUPPLEMENTARY INFORMATION:**

**Background**

The final regulation (TD 9597) that is the subject of this correction is under section 274 of the Internal Revenue Code.

**Need for Correction**

As published, TD 9597 contains an error that may prove to be misleading and is in need of clarification.

**Correction of Publication**

Accordingly, the publication of the final regulation (TD 9597) that was the subject of FR Doc. 2012-18693, is corrected as follows:

On page 45480, column 1, under the caption **DATES:** line five, the language "1.274-9(e), and 1.274-10(h)" is corrected to read "1.274-9(e), and 1.274-10(g)".

**LaNita Van Dyke,**

*Chief, Legal Processing Division, Associate Chief Counsel, Procedure and Administration.*

[FR Doc. 2012-20436 Filed 8-20-12; 8:45 am]

**BILLING CODE 4830-01-P**

**DEPARTMENT OF HOMELAND SECURITY**

**Coast Guard**

**33 CFR Parts 100 and 165**

[Docket No. USCG-2011-0551]

**RIN 1625-AA00; 1625-AA08**

**Special Local Regulation and Safety Zone; America's Cup World Series Regattas, San Francisco Bay; San Francisco, CA**

**AGENCY:** Coast Guard, DHS.

**ACTION:** Temporary final rule.

**SUMMARY:** The Coast Guard has established a special local regulation and a safety zone for sailing events scheduled to occur on the waters of San Francisco Bay adjacent to the City of San Francisco waterfront in the vicinity of the Golden Gate Bridge and Alcatraz Island. This rule will revise the start time for enforcement on August 26, 2012, to 11:30 a.m. instead of noon. This