

(ASNT) Level II or equivalent, eddy current inspect each M/R blade for a crack or a nick in accordance with paragraph number 4 and paragraph number 7 through 17 of Technique Number ET002, dated November 2007, attached to Brantly International, Inc., Service Bulletin No. 111, dated February 10, 2011 (SB 111).

(ii) Thereafter, at intervals not to exceed 300 hours TIS or five calendar years, whichever occurs first, repeat the eddy current inspection in accordance with the requirements of paragraph (d)(2)(i) of this AD.

(iii) Using a metallic coin or tap hammer, tap inspect each M/R blade for delamination in the bonded areas as shown on SB 111, Section 4. Pay particular attention to the root area in the first 12 inches of the top and bottom of each M/R blade.

(iv) Using a 10X or higher power magnifying glass, visually inspect for a crack, nick, crease, wrinkle, bend, extra hole (such as a stop drill hole), extra rivet, and any inadequate rivet spacing caused by additional holes or rivets.

(v) Thereafter, at intervals not to exceed 25 hours TIS, repeat the tap inspection in accordance with the requirements of paragraph (d)(2)(iii) of this AD and the visual inspection using a 10X or higher power magnifying glass in accordance with the requirements of paragraph (d)(2)(iv) of this AD.

(3) Before further flight, remove from service any M/R blade with a crack, nick, crease, wrinkle, bend, extra hole, extra rivet, delamination, or inadequate rivet spacing caused by additional holes or rivets.

(e) Alternative Methods of Compliance (AMOC)

(1) The Manager, Safety Management Group, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send your proposal to: Marc Belhumeur, Senior Project Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5177; email marc.belhumeur@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(f) Additional Information

For service information identified in this AD, contact Brantly International, Inc., 621 South Royal Lane, Suite 100, Coppell Texas 75019, telephone (972) 829-4638, email tarcher@superiorairparts.com. You may

review a copy of this information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(g) Subject

Joint Aircraft Service Component (JASC)
Code: 6210, Main Rotor Blade.

Issued in Fort Worth, Texas, on October 5, 2012.

Kim Smith,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2012-25444 Filed 10-15-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-130266-11]

RIN 1545-BK57

Additional Requirements for Charitable Hospitals; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Change of date of public hearing on proposed rulemaking.

SUMMARY: This document changes the date of a public hearing on proposed regulations that provide guidance regarding the requirements for charitable hospital organizations relating to financial assistance and emergency medical care policies, charges for certain care provided to individuals eligible for financial assistance, and billing and collections. **DATES:** The public hearing originally scheduled for Monday, October 29, 2012, at 10 a.m. is rescheduled for Wednesday, December 5, 2012, at 10 a.m. Outlines of topics to be discussed at the public hearing must be received by November 7, 2012.

ADDRESSES: The public hearing is being held in the IRS Auditorium, Internal Revenue Service Building, 1111 Constitution Avenue NW., Washington, DC 20224. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present photo identification to enter the building.

Send Submissions to CC:PA:LPD:PR (REG-130266-11), Room 5205, Internal

Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday to CC:PA:LPD:PR (REG-130266-11), Couriers Desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC or sent electronically via the Federal eRulemaking Portal at www.regulations.gov (REG-130266-11).

FOR FURTHER INFORMATION CONTACT:

Concerning the regulations, Amber L. Mackenzie or Preston J. Quesenberry at (202) 622-6070; concerning submissions of comments, the hearing and/or to be placed on the building access list to attend the hearing Oluwafunmilayo Taylor at (202) 622-7180 (not toll-free numbers).

SUPPLEMENTARY INFORMATION: A notice of public hearing on proposed rulemaking appearing in the **Federal Register** on Monday, October 1, 2012 (77 FR 59878), announced that a public hearing on proposed regulations regarding the requirements for charitable hospital organizations, would be held on Monday, October 29, 2012, beginning at 10 a.m. in the auditorium of the Internal Revenue Service Building at 1111 Constitution Avenue NW., Washington, DC.

Because of access restrictions, the IRS will not admit visitors beyond the immediate entrance area more than 30 minutes before the hearing starts. For information about having your name placed on the building access list to attend the hearing, see the **FOR FURTHER INFORMATION CONTACT** section of this document.

The date of the public hearing has been changed. The hearing is now scheduled for Wednesday, December 5, 2012, beginning at 10 a.m. in the auditorium of the Internal Revenue Service at 1111 Constitution Avenue NW., Washington, DC. Outlines of topics to be discussed at the public hearing must be received by November 7, 2012.

LaNita Van Dyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. 2012-25298 Filed 10-15-12; 8:45 am]

BILLING CODE 4830-01-P