

whichever occurs first, replace the accumulator with a new non-suspect accumulator, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-32-172, dated March 15, 2011.

(h) Retained Parts Installation Prohibition

This paragraph restates the requirements of paragraph (h) of AD 2012-14-04, Amendment 39-17118 (77 FR 42956, July 23, 2012), with no changes. As of August 27, 2012 (the effective date of AD 2012-14-04), no person may install a parking brake accumulator, P/N 0860162001 or 0860162002 with a serial number that is not listed in the table in paragraph 3.B.(2) of Bombardier Service Bulletin 8-32-170, dated February 25, 2011, on any airplane.

(i) New Requirement of this AD: Install Restraint Devices on All Airplanes

Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first: Install restraint devices around the parking brake hydraulic accumulator end caps by incorporating Bombardier ModSum 8Q101901, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-32-169, Revision A, dated December 16, 2011.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (i) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8-32-169, dated November 25, 2011, which is not incorporated by reference in this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

(1) Refer to MCAI Canadian Airworthiness Directive CF-2011-29R1, dated May 24, 2012; and the service information identified in paragraphs (m)(1)(i) through (m)(1)(v) of this AD; for related information.

(i) Bombardier Service Bulletin 8-32-169, Revision A, dated December 16, 2011.

(ii) Bombardier Service Bulletin 8-32-170, dated February 25, 2011.

(iii) Bombardier Service Bulletin 8-32-172, dated March 15, 2011.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on March 5, 2013.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-05813 Filed 3-25-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-1345; Airspace Docket No. 12-ANM-31]

Proposed Modification of Class D and Class E Airspace and Establishment of Class E Airspace; Pasco, WA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E surface airspace at Tri-Cities Airport, Pasco, WA. Controlled airspace is necessary to accommodate aircraft using Area Navigation (RNAV) Global Positioning System (GPS) standard instrument approach procedures at Tri-Cities Airport, Pasco, WA. This action also would modify the Class D airspace and Class E airspace by adjusting the geographic coordinates of Tri-Cities Airport and Kennewick, Vista Field Airport. This will also correct the airport name from Vista Airport, Kennewick, WA to Kennewick, Vista Field Airport, WA. The FAA is proposing this action to enhance the safety and management of aircraft operations at Tri-Cities Airport, Pasco, WA.

DATES: Comments must be received on or before May 10, 2013.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590; telephone (202) 366-9826. You must identify FAA Docket No. FAA-2012-1345; Airspace Docket No. 12-ANM-31, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT: Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA 2012-1345 and Airspace Docket No. 12-ANM-31) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2012-1345 and Airspace Docket No. 12-ANM-31". The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned

with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Center, Operations Support Group, 1601 Lind Avenue SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) Part 71 by establishing Class E surface airspace at Tri-Cities Airport, Pasco, WA. Controlled airspace is necessary to accommodate aircraft using RNAV (GPS) standard instrument approach procedures at Tri-Cities Airport, Pasco, WA. Also, the geographic coordinates of Tri-Cities Airport and Kennewick, Vista Field Airport would be updated to coincide with the FAA's aeronautical database for the Class D airspace and Class E airspace designated as an extension to Class D surface area, and Class E airspace extending upward from 700 feet above the surface, at Pasco, WA. This action would enhance the safety and management of aircraft operations at Tri-Cities Airport, Pasco, WA. This will also correct the name from Vista Airport, Kennewick, WA to Kennewick, Vista Field Airport, WA.

Class E airspace designations are published in paragraphs 5000, 6002, 6004 and 6005, respectively, of FAA Order 7400.9W, dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The Class D and Class E airspace designations listed in this document

will be published subsequently in this Order.

The FAA has determined this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation; (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority for the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish controlled airspace at Tri-Cities Airport, Pasco, WA.

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9W, Airspace Designations and Reporting Points, dated August 8, 2012, and effective September 15, 2012 is amended as follows:

Paragraph 5000 Class D airspace.

* * * * *

ANM WA D Pasco, WA [Modified]

Pasco, Tri-Cities Airport, WA
(lat. 46°15'53" N., long. 119°07'09" W.)
Kennewick, Vista Field Airport, WA
(lat. 46°13'07" N., long. 119°12'36" W.)

That airspace extending upward from the surface to and including 2,900 feet MSL within a 4.3-mile radius of the Tri-Cities Airport, excluding that airspace within a 2-mile radius of the Vista Field Airport. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Paragraph 6002 Class E Airspace Designated as Surface Areas.

* * * * *

ANM WA E2 Pasco, WA [New]

Pasco, Tri-Cities Airport, WA
(lat. 46°15'53" N., long. 119°07'09" W.)
Kennewick, Vista Field Airport, WA
(lat. 46°13'07" N., long. 119°12'36" W.)

Within a 4.3-mile radius of the Tri-Cities Airport, excluding that airspace within a 2-mile radius of the Vista Field Airport. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Paragraph 6004 Class E airspace designated as an extension to a Class D surface area.

* * * * *

ANM WA E4 Pasco, WA [Modified]

Pasco, Tri-Cities Airport, WA
(Lat. 46°15'53" N., long. 119°07'09" W.)
Pasco VOR/DME
(Lat. 46°15'47" N., long. 119°06'57" W.)
LOM
(Lat. 46°20'17" N., long. 119°00'45" W.)

That airspace extending upward from the surface within 3.5 miles each side of the Pasco ILS localizer northeast course extending from the 4.3-mile radius of Tri-Cities Airport to 8.7 miles northeast of the LOM, and within 2.7 miles each side of the Pasco VOR/DME 131° radial extending from the 4.3-mile radius of the airport to 7 miles southeast of the VOR/DME. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM WA E5 Pasco, WA [Modified]

Pasco, Tri-Cities Airport, WA
(Lat. 46°15'53" N., long. 119°07'09" W.)

Pasco VOR/DME
(Lat. 46°15'47" N., long. 119°06'57" W.)

Richland Airport, WA
(Lat. 46°18'20" N., long. 119°18'15" W.)

That airspace extending upward from 700 feet above the surface within 9.2 miles northwest and 5.3 miles southeast of the Pasco VOR/DME 046° and 226° radials extending from 20.1 miles northeast to 10.5 miles southwest of the VOR/DME, and within 8.3 miles northeast and 6.1 miles southwest of the Pasco VOR/DME 131° radial extending from the VOR/DME to 26.3 miles southeast of the VOR/DME, and within 4.3 miles north and 6.6 miles south of the Pasco VOR/DME 288° radial extending from 7 miles west of the VOR/DME to 23.1 miles west of the VOR/DME, and within 8.3 miles west and 4 miles east of the 026° bearing of the Richland Airport extending 20.9 miles northeast of the Richland Airport; that airspace extending upward from 1,200 feet above the surface bounded by a line beginning at lat. 45°49'00" N., long. 118°00'00" W.; thence to lat. 45°49'00" N., long. 119°45'00" W.; to lat. 47°00'00" N., long. 119°45'00" W.; to lat. 47°00'00" N., long., 118°00'00" W.; thence to the point of origin.

Issued in Seattle, Washington, on March 18, 2013.

Clark Desing,

Manager, Operations Support Group, Western Service Center.

[FR Doc. 2013-06943 Filed 3-25-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2011-1111; Airspace Docket No. 11-ASW-13]

Proposed Amendment of Class E Airspace; Gruver, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Gruver, TX. Controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAP) at Gruver Municipal Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations for SIAPs at the airport.

DATES: 0901 UTC. Comments must be received on or before May 10, 2013.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2011-1111/Airspace Docket No. 11-ASW-13, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2011-1111/Airspace Docket No. 11-ASW-13." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/

[air_traffic/publications/airspace_amendments/](http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Central Service Center, 2601 Meacham Blvd., Fort Worth, TX 76137.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by amending Class E airspace extending upward from 700 feet above the surface to ensure that required controlled airspace extending from the 6.5-mile radius of the airport to 9.6 miles southwest of the airport is available to contain aircraft executing new standard instrument approach procedures at Gruver Municipal Airport, Gruver, TX. Controlled airspace is needed for the safety and management of IFR operations at the airport.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9W, dated August 8, 2012 and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.