

TABLE 3 TO PARAGRAPH (g) OF THIS AD: FOR MODEL A330–223F AIRPLANES

Compliance time	Torque check interval (not to exceed)
Within 2,140 flight cycles or 6,600 flight hours, whichever occurs first since the last torque check performed as specified in Pratt & Whitney Alert Service Bulletin PW4G–100–A71–32, or since airplane first flight, as applicable.	2,140 flight cycles or 6,600 flight hours, whichever occurs first.

(2) If any loose or broken bolt is detected during the check required by paragraph (g)(1) of this AD, before further flight, replace all four forward engine mount bolts and associated nuts, on the engine where the loose or broken bolt was detected, with new bolts and nuts, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–71–3028, Revision 01, dated February 20, 2012.

(3) Replacement of bolts and nuts as required by paragraph (g)(2) of this AD is not terminating action for the repetitive torque checks required by paragraph (g)(1) of this AD.

**(h) Compliance with AD 2006–16–05, Amendment 39–14705 (71 FR 44185, August 4, 2006)**

Doing the actions required by paragraph (g) of this AD constitutes compliance with the requirements specified in paragraph (g) of AD 2006–16–05, Amendment 39–14705 (71 FR 44185, August 4, 2006).

**(i) Parts Installation Prohibition**

As of the effective date of this AD, no person may install any INCO718 material, forward mount pylon bolt having Pratt & Whitney P/N 54T670 on any airplane.

**(j) Credit for Previous Actions**

This paragraph provides credit for the actions required by paragraphs (g)(1) and (g)(2) of this AD, if those actions were performed before the effective date of this AD using Airbus Mandatory Service Bulletin A330–71–3028, dated December 16, 2011, which is not incorporated by reference in this AD.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone (425) 227–1138; fax (425) 227–1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding

district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(l) Related Information**

(1) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2012–0094, dated May 31, 2012; and Airbus Mandatory Service Bulletin A330–71–3028, Revision 01, dated February 20, 2012.

(2) For Airbus service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on March 20, 2013.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013–07203 Filed 3–27–13; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

**[Docket No. FAA–2013–0158; Airspace Docket No. 13–ASO–5]**

**Proposed Amendment of Class E Airspace; Tuskegee, AL**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend Class E Airspace at Tuskegee, AL, as the Tuskegee VOR/DME has been decommissioned and airspace reconfiguration is necessary for the safety and airspace management of

Instrument Flight Rules (IFR) operations at Moten Field Municipal Airport. This action also would amend the airport's name.

**DATES:** Comments must be received on or before May 13, 2013.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey SE., Washington, DC 20590–0001; Telephone: 1–800–647–5527; Fax: 202–493–2251. You must identify the Docket Number FAA–2013–0158; Airspace Docket No. 13–ASO–5, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2013–0158; Airspace Docket No. 13–ASO–5) and be submitted in triplicate to the Docket Management System (see “ADDRESSES” section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: “Comments to Docket No. FAA–2013–0158; Airspace Docket No. 13–ASO–5.” The postcard

will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports/airtraffic/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11-2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

#### The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 by modifying Class E airspace extending upward from 700 feet above the surface to within a 6.7-mile radius of Moten Field Municipal Airport, Tuskegee, AL, formerly called Tuskegee Municipal Airport. Airspace reconfiguration is necessary due to the decommissioning of the Tuskegee VOR/DME and cancellation of the VOR approach, and for continued safety and management of IFR operations at the airport. Accordingly, the extension of Class E airspace to the northeast of the airport would be eliminated.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.9W, dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR

71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it would amend Class E airspace at Moten Field Municipal Airport, Tuskegee, AL.

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

#### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

#### **§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9W, Airspace Designations and Reporting Points, dated August 8, 2012, effective September 15, 2012, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

#### **ASO TN E5 Tuskegee, AL [Amended]**

Moten Field Municipal Airport, AL  
(Lat. 32°27'38" N., long. 85°40'48" W.)

That airspace extending upward from 700 feet above the surface within a 6.7-mile radius of Moten Field Municipal Airport.

Issued in College Park, Georgia, on March 20, 2013.

**Barry A. Knight,**

*Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2013-07115 Filed 3-27-13; 8:45 am]

**BILLING CODE 4910-13-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 71**

[Docket No. FAA-2012-0792; Airspace Docket No. 12-ANE-13]

#### **Proposed Establishment of Class E Airspace; Boothbay, ME**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish Class E Airspace at Boothbay, ME, to accommodate a new Area Navigation (RNAV) Global Positioning System (GPS) special Standard Instrument Approach Procedure (SIAP) serving St. Andrews Hospital Heliport. This action would enhance the safety and airspace management of Instrument Flight Rules (IFR) operations within the National Airspace System.

**DATES:** Comments must be received on or before May 13, 2013.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2012-0792;