

# Rules and Regulations

Federal Register

Vol. 78, No. 237

Tuesday, December 10, 2013

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF AGRICULTURE

### Animal and Plant Health Inspection Service

#### 9 CFR Parts 92, 93, 94, 95, 96, and 98

[Docket No. APHIS–2008–0010]

RIN 0579–AC68

#### Bovine Spongiform Encephalopathy; Importation of Bovines and Bovine Products

##### Corrections

In rule document 2013–28228 appearing on pages 72980–73008 in the issue of December 4, 2013, make the following corrections:

1. On page 72985, in the third column, in the 16th line from the bottom “C□N” should read “CAN”.

##### § 93.418 [Corrected]

2. On page 72996, in the second column, in the 10th line from the bottom, “C□N” should read “CAN”.

3. On the same page, in the third column, in the 1st line “CN” should read “CAN”.

[FR Doc. C1–2013–28228 Filed 12–9–13; 8:45 am]

BILLING CODE 1505–01–D

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 25

[Docket No. FAA–2013–1034; Special Conditions No. 25–508–SC]

#### Special Conditions: Cessna Model 680 Series Airplanes; Aircraft Electronic System Security Protection From Unauthorized External Access

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special condition; request for comments.

**SUMMARY:** These special conditions are issued for the Cessna Model 680 Series airplanes. These airplanes will have a novel or unusual design feature associated with the architecture and connectivity capabilities of the airplanes’ computer systems and networks. Connectivity to, or access by, external systems and networks may result in security vulnerabilities to the airplanes’ systems.

The proposed network architecture includes the following connectivity between systems:

1. Airplane control, communication, display, monitoring and navigation systems,
2. Operator business and administrative support systems, and
3. Passenger entertainment systems, and access by systems external to the airplane.

The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

**DATES:** The effective date of these special conditions is December 10, 2013. We must receive your comments by January 24, 2014.

**ADDRESSES:** Send comments identified by docket number [FAA–2013–XXXX] using any of the following methods:

- *Federal regulations Portal:* Go to <http://www.regulations.gov/> and follow the online instructions for sending your comments electronically.

*Mail:* Send comments to Docket Operations, M–30, U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE., Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

*Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 8 a.m. and 5 p.m., Monday through Friday, except federal holidays.

*Fax:* Fax comments to Docket Operations at 202–493–2251.

*Privacy:* The FAA will post all comments it receives, without change, to <http://www.regulations.gov/>, including any personal information the commenter provides. Using the search

function of the docket Web site, anyone can find and read the electronic form of all comments received into any FAA docket, including the name of the individual sending the comment (or signing the comment for an association, business, labor union, etc.). DOT’s complete Privacy Act Statement can be found in the **Federal Register** published on April 11, 2000 (65 FR 19477–19478), as well as at <http://DocketsInfo.dot.gov/>.

*Docket:* Background documents or comments received may be read at <http://www.regulations.gov/> at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except federal holidays.

**FOR FURTHER INFORMATION CONTACT:** Varun Khanna, FAA, Airplane and Flight Crew Interface Branch, ANM–111, Transport Airplane Directorate, Aircraft Certification Service, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone 425–227–1298; facsimile 425–227–1149.

**SUPPLEMENTARY INFORMATION:** The FAA has determined that notice of, and opportunity for prior public comment on, these special conditions are impracticable because these procedures would significantly delay issuance of the design approval and thus delivery of the affected aircraft. The FAA has also determined that notice of these special conditions is unnecessary because the substance of these special conditions has been subject to the public comment process in several prior instances with no substantive comments received. The FAA therefore finds that good cause exists for making these special conditions effective upon publication in the **Federal Register**.

#### Comments Invited

We invite interested people to take part in this rulemaking by sending written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data.

We will consider all comments we receive by the closing date for comments. We may change these special