

**FEDERAL COMMUNICATIONS COMMISSION**

[OMB 3060-0991]

**Information Collection Being Reviewed by the Federal Communications Commission****AGENCY:** Federal Communications Commission.**ACTION:** Notice and request for comments.

**SUMMARY:** As part of its continuing effort to reduce paperwork burdens, and as required by the Paperwork Reduction Act (PRA) of 1995 (44 U.S.C. 3501-3520), the Federal Communications Commission (FCC or the Commission) invites the general public and other Federal agencies to take this opportunity to comment on the following information collection. Comments are requested concerning: whether the proposed collection of information is necessary for the proper performance of the functions of the Commission, including whether the information shall have practical utility; the accuracy of the Commission's burden estimate; ways to enhance the quality, utility, and clarity of the information collected; ways to minimize the burden of the collection of information on the respondents, including the use of automated collection techniques or other forms of information technology; and ways to further reduce the information collection burden on small business concerns with fewer than 25 employees.

The FCC may not conduct or sponsor a collection of information unless it displays a currently valid control number. No person shall be subject to any penalty for failing to comply with a collection of information subject to the PRA that does not display a valid Office of Management and Budget (OMB) control number.

**DATES:** Written PRA comments should be submitted on or before December 8, 2014. If you anticipate that you will be submitting comments, but find it difficult to do so within the period of time allowed by this notice, you should advise the contact listed below as soon as possible.

**ADDRESSES:** Direct all PRA comments to Cathy Williams, FCC, via email [PRA@fcc.gov](mailto:PRA@fcc.gov) and to [Cathy.Williams@fcc.gov](mailto:Cathy.Williams@fcc.gov).

**FOR FURTHER INFORMATION CONTACT:** For additional information about the information collection, contact Cathy Williams at (202) 418-2918.

**SUPPLEMENTARY INFORMATION:**

*OMB Control Number:* 3060-0991.  
*Title:* AM Measurement Data.

*Form Number:* N/A.  
*Type of Review:* Extension of a currently approved collection.  
*Respondents:* Business or other for-profit entities.

*Number of Respondents and Responses:* 1,900 respondents; 3,335 responses.

*Estimated Hours per Response:* 0.50-25 hours.

*Frequency of Response:* Recordkeeping requirement, Third party disclosure requirement, On occasion reporting requirement.

*Total Annual Burden:* 20,780 hours.

*Total Annual Cost:* \$2,171,500.

*Obligation to Respond:* Required to obtain or retain benefits. The statutory authority for this collection of information is contained in Section 154(i) of the Communications Act of 1934, as amended.

*Nature and Extent of Confidentiality:* There is no need for confidentiality treatment with this collection of information.

*Privacy Impact Assessment:* No impact(s).

*Needs and Uses:* The following information collection requirements are contained in this collection:

47 CFR 73.54(c) requires that AM licensees file a letter notification with the FCC when determining power by the direct method. In addition, Section 73.54(c) requires that background information regarding antenna resistance measurement data for AM stations must be kept on file at the station.

47 CFR 73.54(d) requires AM stations using direct reading power meters to either submit the information required by (c) or submit a statement indicating that such a meter is being used.

47 CFR 73.61(a) states each AM station using a directional antenna with monitoring point locations specified in the instrument of authorization must make field strength measurements at the monitoring point locations specified in the instrument of authorization, as often as necessary to ensure that the field at those points does not exceed the values specified in the station authorization. Additionally, stations not having an approved sampling system must make the measurements once each calendar quarter at intervals not exceeding 120 days. The provision of this paragraph supersedes any schedule specified on a station license issued prior to January 1, 1986. The results of the measurements are to be entered into the station log pursuant to the provisions of Section 73.1820.

47 CFR 73.61(b) states if the AM license was granted on the basis of field strength measurements performed

pursuant to Section 73.151(a), partial proof of performance measurements using the procedures described in Section 73.154 must be made whenever the licensee has reason to believe that the radiated field may be exceeding the limits for which the station was most recently authorized to operate.

47 CFR 73.61(c) requires a station may be directed to make a partial proof of performance by the FCC whenever there is an indication that the antenna is not operating as authorized.

47 CFR 73.62(b) requires an AM station with a directional antenna system to measure and log every monitoring point at least once for each mode of directional operation within 24 hours of detection of variance of operating parameters from allowed tolerances.

47 CFR 73.68(c) states a station having an antenna sampling system constructed according to the specifications given in paragraph (a) of this section may obtain approval of that system by submitting an informal letter request to the FCC in Washington, DC, Attention: Audio Division, Media Bureau. The request for approval, signed by the licensee or authorized representative, must contain sufficient information to show that the sampling system is in compliance with all requirements of paragraph (a) of this section.

47 CFR 73.68(d) states in the event that the antenna monitor sampling system is temporarily out of service for repair or replacement, the station may be operated, pending completion of repairs or replacement, for a period not exceeding 120 days without further authority from the FCC if all other operating parameters and the field monitoring point values are within the limits specified on the station authorization.

47 CFR 73.68(e)(1) Special Temporary Authority (see Section 73.1635) shall be requested and obtained from the Commission's Audio Division, Media Bureau in Washington to operate with parameters at variance with licensed values pending issuance of a modified license specifying parameters subsequent to modification or replacement of components.

47 CFR 73.68(e)(4) states request for modification of license shall be submitted to the FCC in Washington, DC, within 30 days of the date of sampling system modification or replacement. Such request shall specify the transmitter plate voltage and plate current, common point current, base currents and their ratios, antenna monitor phase and current indications, and all other data obtained pursuant to this paragraph.

47 CFR 73.68(f) states if an existing sampling system is found to be patently of marginal construction, or where the performance of a directional antenna is found to be unsatisfactory, and this deficiency reasonably may be attributed, in whole or in part, to inadequacies in the antenna monitoring system, the FCC may require the reconstruction of the sampling system in accordance with requirements specified above.

47 CFR 73.69(c) requires AM station licensees with directional antennas to file an informal request to operate without required monitors with the Media Bureau in Washington, DC, when conditions beyond the control of the licensee prevent the restoration of an antenna monitor to service within a 120 day period. This request is filed in conjunction with Section 73.3549.

47 CFR 73.69(d)(1) requires that AM licensees with directional antennas request to obtain temporary authority to operate with parameters at variance with licensed values when an authorized antenna monitor is replaced pending issuance of a modified license specifying new parameters.

47 CFR 73.69(d)(5) requires AM licensees with directional antennas to submit an informal request for modification of license to the FCC within 30 days of the date of antenna monitor replacement.

47 CFR 73.151(c)(1)(ix) states the orientation and distances among the individual antenna towers in the array shall be confirmed by a post-construction certification by a land surveyor (or, where permitted by local regulation, by an engineer) licensed or registered in the state or territory where the antenna system is located.

47 CFR 73.151(c)(2)(i) describes techniques for moment method modeling, sampling system construction, and measurements that must be taken as part of a moment method proof. A description of the sampling system and the specified measurements must be filed with the license application.

47 CFR 73.151(c)(3) states reference field strength measurement locations shall be established in directions of pattern minima and maxima. On each radial corresponding to a pattern minimum or maximum, there shall be at least three measurement locations. The field strength shall be measured at each reference location at the time of the proof of performance. The license application shall include the measured field strength values at each reference point, along with a description of each measurement location, including GPS coordinates and datum reference.

47 CFR 73.154 requires the result of the most recent partial proof of performance measurements and analysis to be retained in the station records and made available to the FCC upon request. Maps showing new measurement points shall be associated with the partial proof in the station's records and shall be made available to the FCC upon request.

47 CFR 73.155 states a station licensed with a directional antenna pattern pursuant to a proof of performance using moment method modeling and internal array parameters as described in § 73.151(c) shall recertify the performance of that directional antenna pattern at least once within every 24 month period.

47 CFR 73.155(c) states the results of the periodic directional antenna performance recertification measurements shall be retained in the station's public inspection file.

47 CFR 73.158(b) requires a licensee of an AM station using a directional antenna system to file a request for a corrected station license when the description of monitoring point in relation to nearby landmarks as shown on the station license is no longer correct due to road or building construction or other changes. A copy of the monitoring point description must be posted with the existing station license.

47 CFR 73.3538(b) requires a broadcast station to file an informal application to modify or discontinue the obstruction marking or lighting of an antenna supporting structure.

47 CFR 73.3549 requires licensees to file with the FCC requests for extensions of authority to operate without required monitors, transmission system indicating instruments, or encoders and decoders for monitoring and generating the Emergency Alert System codes. Such requests must contain information as to when and what steps were taken to repair or replace the defective equipment and a brief description of the alternative procedures being used while the equipment is out of service.

Federal Communications Commission.

**Marlene H. Dortch,**

*Secretary, Office of the Secretary, Office of the Managing Director.*

[FR Doc. 2014-23820 Filed 10-6-14; 8:45 am]

**BILLING CODE 6712-01-P**

---

## FEDERAL RESERVE SYSTEM

### Formations of, Acquisitions by, and Mergers of Bank Holding Companies

The companies listed in this notice have applied to the Board for approval,

pursuant to the Bank Holding Company Act of 1956 (12 U.S.C. 1841 *et seq.*) (BHC Act), Regulation Y (12 CFR Part 225), and all other applicable statutes and regulations to become a bank holding company and/or to acquire the assets or the ownership of, control of, or the power to vote shares of a bank or bank holding company and all of the banks and nonbanking companies owned by the bank holding company, including the companies listed below.

The applications listed below, as well as other related filings required by the Board, are available for immediate inspection at the Federal Reserve Bank indicated. The applications will also be available for inspection at the offices of the Board of Governors. Interested persons may express their views in writing on the standards enumerated in the BHC Act (12 U.S.C. 1842(c)). If the proposal also involves the acquisition of a nonbanking company, the review also includes whether the acquisition of the nonbanking company complies with the standards in section 4 of the BHC Act (12 U.S.C. 1843). Unless otherwise noted, nonbanking activities will be conducted throughout the United States.

Unless otherwise noted, comments regarding each of these applications must be received at the Reserve Bank indicated or the offices of the Board of Governors not later than October 30, 2014.

A. Federal Reserve Bank of Kansas City (Dennis Denney, Assistant Vice President) 1 Memorial Drive, Kansas City, Missouri 64198-0001:

1. *Little London Bancorp*, Colorado Springs, Colorado; to become a bank holding company by acquiring 100 percent of the voting shares of 5Star Bank, Colorado Springs, Colorado.

Board of Governors of the Federal Reserve System, October 1, 2014.

**Michael J. Lewandowski,**

*Associate Secretary of the Board.*

[FR Doc. 2014-23874 Filed 10-6-14; 8:45 am]

**BILLING CODE 6210-01-P**

---

## FEDERAL RESERVE SYSTEM

### Formations of, Acquisitions by, and Mergers of Bank Holding Companies

The companies listed in this notice have applied to the Board for approval, pursuant to the Bank Holding Company Act of 1956 (12 U.S.C. 1841 *et seq.*) (BHC Act), Regulation Y (12 CFR Part 225), and all other applicable statutes and regulations to become a bank holding company and/or to acquire the assets or the ownership of, control of, or the power to vote shares of a bank or bank holding company and all of the