

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2014-0876; Directorate Identifier 2014-CE-032-AD]

RIN 2120-AA64

Airworthiness Directives; Costruzioni Aeronautiche Tecnam srl Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Costruzioni Aeronautiche Tecnam srl Model P2006T airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as cracking found in the engine exhaust pipe. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 15, 2014.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Costruzioni Aeronautiche Tecnam Airworthiness Office, Via Maiorise-81043 Capua (CE) Italy; telephone: +39 0823 997538; fax: +39 0823 622899; email: technical.support@tecnam.com; Internet: <http://www.tecnam.com/Customer-Care/Service-Bulletins.aspx>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the

availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0876; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0876; Directorate Identifier 2014-CE-032-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2014-0220, dated September 30, 2014 (referred to after this as "the MCAI"), to correct an unsafe condition for Costruzioni Aeronautiche Tecnam srl Model P2006T airplanes. The MCAI states:

During a pre-flight inspection of a P2006T aeroplane, which included the opening of engine nacelle, a crack was found on the engine exhaust pipe Part Number (P/N) 26-7-1800-1.

This condition, if not detected and corrected, could lead to engine damage, possibly resulting in damage to the aeroplane and injury to the occupants.

To address this potential unsafe condition, Costruzioni Aeronautiche Tecnam issued Service Bulletin (SB) SB 170-CS-Ed 1 Rev1.

For the reason described above, this AD requires a one-time inspection of the affected engine exhaust pipes and, depending on findings, replacement.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0876.

Relevant Service Information

Costruzioni Aeronautiche Tecnam srl has issued Mandatory Service Bulletin No. SB 170-CS-ED 1, Rev 1, dated September 25, 2014. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 10 products of U.S. registry. We also estimate that it would take about .5 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$425, or \$42.50 per product.

In addition, we estimate that any necessary follow-on actions would take about .5 work-hour and require parts costing \$343, for a cost of \$385.50 per product. We have no way of determining the number of products that may need these actions.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of

information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591. ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Amend § 39.13 by adding the following new AD:

Costruzioni Aeronautiche Tecnam srl:

Docket No. FAA–2014–0876; Directorate Identifier 2014–CE–032–AD.

(a) Comments Due Date

We must receive comments by December 15, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Costruzioni Aeronautiche Tecnam srl P2006T airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 78: Engine Exhaust.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as cracking found in the engine exhaust pipe. We are issuing this proposed AD to detect and correct cracked engine exhaust pipes, which could lead to engine damage, possibly resulting in damage to the airplane and injury to the occupants.

(f) Actions and Compliance

Unless already done, do the following actions as specified in paragraphs (f)(1) through (f)(3) of this AD:

- (1) Within 25 hours time-in-service (TIS) after the effective date of this AD or within the next 30 days after the effective date of this AD, whichever occurs first, do a detailed inspection of all engine exhaust pipes following the inspection instructions in Costruzioni Aeronautiche Tecnam Service Bulletin No. SB 170–CS–ED 1, Rev 1, dated September 25, 2014.

(2) If any deformation, cracks, or any other defects are detected during the inspection as

required by paragraph (f)(1) of this AD, before further flight, replace the affected pipe with an airworthy part or contact Costruzioni Aeronautiche Tecnam for FAA-approved repair instructions approved specifically for compliance with this AD and incorporate those instructions.

(3) Within 30 days after the inspection required by paragraph (f)(1) of this AD or within 30 days after the effective date of this AD, whichever occurs later, report the results (including no findings) by using the occurrence report in Costruzioni Aeronautiche Tecnam Service Bulletin No. SB 170–CS–ED 1, Rev 1, dated September 25, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4119; fax: (816) 329–4090; email: albert.mercado@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(h) Related Information

Refer to European Aviation Safety Agency (EASA) AD No.: 2014–0220, dated September 30, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–0876. For

service information related to this AD, contact Costruzioni Aeronautiche Tecnam Airworthiness Office, Via Maiorise-81043 Capua (CE) Italy; telephone: +39 0823 997538; fax: +39 0823 622899; email: technical.support@tecnam.com; Internet: <http://www.tecnam.com/Custom-Care/Service-Bulletins.aspx>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on October 22, 2014.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-25740 Filed 10-28-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Part 1308

[Docket No. DEA-400]

Schedules of Controlled Substances: Removal of Naloxegol From Control

AGENCY: Drug Enforcement Administration, Department of Justice.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Drug Enforcement Administration (DEA) proposes to remove naloxegol ((5 α ,6 α)-17-allyl-6-((20-hydroxy-3,6,9,12,15,18-hexaoxaicos-1-yl)oxy)-4,5-epoxymorphinon-3,14-diol) and its salts from the schedules of the Controlled Substances Act (CSA). This scheduling action is pursuant to the CSA which requires that such actions be made on the record after opportunity for a hearing through formal rulemaking. Naloxegol is currently a schedule II controlled substance because it can be derived from opium alkaloids. This action would remove the regulatory controls and administrative, civil, and criminal sanctions applicable to controlled substances, including those specific to schedule II controlled substances, on persons who handle (manufacture, distribute, reverse distribute, dispense, conduct research, import, export, or conduct chemical analysis) or propose to handle naloxegol.

DATES: Interested persons may file written comments on this proposal in accordance with 21 CFR 1308.43(g). Electronic comments must be submitted, and written comments must be postmarked, on or before November 28, 2014. Commenters should be aware

that the electronic Federal Docket Management System will not accept comments after 11:59 p.m. Eastern Time on the last day of the comment period.

Interested persons, defined at 21 CFR 1300.01 as those “adversely affected or aggrieved by any rule or proposed rule issuable pursuant to section 201 of the Act (21 U.S.C. 811)”, may file a request for hearing or waiver of participation pursuant to 21 CFR 1308.44 and in accordance with 21 CFR 1316.45, 1316.47, 1316.48, or 1316.49, as applicable. Requests for hearing, notices of appearance, and waivers of an opportunity for a hearing or to participate in a hearing must be received on or before November 28, 2014.

ADDRESSES: To ensure proper handling of comments, please reference “Docket No. DEA-400” on all correspondence, including any attachments.

- **Electronic comments:** The DEA encourages that all comments be submitted through the Federal eRulemaking Portal, which provides the ability to type short comments directly into the comment field on the Web page or to attach a file for lengthier comments. Please go to <http://www.regulations.gov> and follow the online instructions at that site for submitting comments. Upon completion of your submission you will receive a Comment Tracking Number for your comment. Please be aware that submitted comments are not instantaneously available for public view on Regulations.gov. If you have received a comment tracking number, your comment has been successfully submitted and there is no need to resubmit the same comment.

- **Paper comments:** Paper comments that duplicate an electronic submission are not necessary and are discouraged. Should you wish to mail a comment *in lieu of* an electronic format, it should be sent via regular or express mail to: Drug Enforcement Administration, Attention: DEA Federal Register Representative/ ODXL, 8701 Morrisette Drive, Springfield, Virginia 22152.

- **Hearing requests:** All requests for hearing and waivers of participation must be sent to: Drug Enforcement Administration, Attn: Hearing Clerk/LJ, 8701 Morrisette Drive, Springfield, Virginia 22152.

FOR FURTHER INFORMATION CONTACT: Imelda L. Paredes, Office of Diversion Control, Drug Enforcement Administration; Mailing Address: 8701 Morrisette Drive, Springfield, Virginia 22152; Telephone: (202) 598-6812.

SUPPLEMENTARY INFORMATION:

Posting of Public Comments

Please note that all comments received in response to this docket are considered part of the public record. They will, unless reasonable cause is given, be made available by the DEA for public inspection online at <http://www.regulations.gov>. Such information includes personal identifying information (such as your name, address, etc.) voluntarily submitted by the commenter. The Freedom of Information Act (FOIA) applies to all comments received. If you want to submit personal identifying information (such as your name, address, etc.) as part of your comment, but do not want it to be made publicly available, you must include the phrase “PERSONAL IDENTIFYING INFORMATION” in the first paragraph of your comment. You must also place the personal identifying information you do not want made publicly available in the first paragraph of your comment and identify what information you want redacted.

If you want to submit confidential business information as part of your comment, but do not want it to be made publicly available, you must include the phrase “CONFIDENTIAL BUSINESS INFORMATION” in the first paragraph of your comment. You must also prominently identify confidential business information to be redacted within the comment.

Comments containing personal identifying information and confidential business information identified as directed above will generally be made publicly available in redacted form. If a comment has so much confidential business information or personal identifying information that it cannot be effectively redacted, all or part of that comment may not be made publicly available. Comments posted to <http://www.regulations.gov> may include any personal identifying information (such as name, address, and phone number) included in the text of your electronic submission that is not identified as directed above as confidential.

An electronic copy of this document and supplemental information to this proposed rule are available at <http://www.regulations.gov> for easy reference. The DEA specifically solicits written comments regarding the DEA’s economic analysis of the impact of these proposed changes. The DEA requests that commenters provide detailed descriptions in their comments of any expected economic impacts, especially to small entities. Commenters should provide empirical data to illustrate the nature and scope of such impact.