

Respondents: There were a total of 129 applications submitted to the FAA in fiscal year (FY) 2019. Out of the 129 applications, 64 applications were submitted for initial certification.

Frequency: Information is collected on occasion. One time for initial certification and when or if an existing certificated repair station request changes to their certificate.

Estimated Average Burden per Response: 15 minutes

Estimated Total Annual Burden: 32.25 hours annual burden for FY2019. There is no requirement for a respondent to submit this form annually.

Issued in Washington, DC, on March 26, 2020.

Susan Traugott Ludwig,

Federal Aviation Administration, Office of Safety Standards, Aviation Safety Inspector Aircraft Maintenance Division, Repair Station Branch, AFS-340.

[FR Doc. 2020-06701 Filed 3-31-20; 8:45 am]

BILLING CODE 4910-13-P

via www.faa.gov, email, in person, or by mail.

The FAA Form 8310-3, Application for Repair Station Certificate and/or Ratings captures information such as, but not limited to; official name of repair station, location where business is conducted, official mailing address, any doing business as name, changes in ratings, or if initial certification, ratings sought, changes in location or housing and facilities, change in name or ownership, or any other purpose for which the applicant requests, including a request for approval to contract maintenance functions to outside entities. The FAA has identified an inaccuracy in how burden calculations are determined associated with initial repair station certifications and subsequent changes to an existing repair station certificate. The FAA has identified that the information collected through the FAA Form 8310-3 does not capture the entire repair station certification activities or changes to an existing certificate. OMB Control Number 2120-0682 is not only authorizing the Agency to receive information collected on the FAA Form 8310-3, but should also encapsulate the entire calculation burden associated with repair station certification and subsequent changes to an existing certificate.

Once burden calculations associated with repair station certification activities are properly assessed, the FAA will publish a new notice to the **Federal Register** capturing the entire burden calculation for repair station certification and subsequent changes to an existing certificate.

DATES: Written comments should be submitted by 60 days from March 20, 2020.

ADDRESSES: Please send written comments:

By Electronic Docket:

www.regulations.gov (Enter docket number into search field).

By mail: Patricia K. Williams, Federal Aviation Administration, AFS-340, 950 L'Enfant Plaza N SW, Washington, DC 20024.

By fax: 202-267-1812.

FOR FURTHER INFORMATION CONTACT: Susan Traugott Ludwig, by email at: susan.traugott.ludwig@faa.gov; phone: 202-267-1684.

SUPPLEMENTARY INFORMATION:

Public Comments Invited: You are asked to comment on any aspect of this information collection, including (a) Whether the proposed collection of information is necessary for FAA's performance; (b) the accuracy of the estimated burden; (c) ways for FAA to

enhance the quality, utility and clarity of the information collection; and (d) ways that the burden could be minimized without reducing the quality of the collected information. The agency will summarize and/or include your comments in the request for OMB's clearance of this information collection.

OMB Control Number: 2120-0682.

Title: Certification of Repair Stations, Part 145 of Title 14, CFR.

Form Numbers: FAA Form 8310-3.

Type of Review: Clearance of a renewal of an information collection.

Background: The FAA's authority to issue rules on aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

Rulemaking was promulgated under the authority described in title 49, subtitle VII, part A, subpart III, section 44701, General requirements, and section 44707, Examining and rating air agencies. Under section 44701, the FAA may prescribe regulations and standards in the interest of safety for inspecting, servicing, and overhauling aircraft, aircraft engines, propellers, and appliances. The FAA may also prescribe equipment and facilities for, and the timing and manner of, inspecting, servicing, and overhauling these items. Under section 44707, the FAA may examine and rate repair stations. 14 Part 145 is within the scope of section 44707.

14 CFR part 145 prescribes the requirements for the issuance of repair station certificates. The FAA Form 8310-3, Application for Repair Station Certificate and/or Rating is available to the applicant who wishes to obtain initial repair station certification or submit changes to an existing air agency certificate. The applicant voluntarily submits the application to the appropriate FAA office by mail or email for review and acceptance. The applicant enters the information required for certification or changes to the existing certificate, which consists of; official name of repair station, location where business is conducted, official mailing address, any doing business as name, changes in ratings, or if initial certification, ratings sought, changes in location or housing and facilities, change in name or ownership, or any other purpose for which the applicant requests, including a request for approval to contract maintenance functions to outside entities. Once the FAA reviews the submitted application and finds the applicant has the ability to comply with the 14 CFR part 145

requirements for certification, an air agency certificate and ratings is issued. The FAA retains a copy of the application in the FAA office that issued the certificate for an indefinite time or a time-period specified by the Agency's Records Management Order 1350.14B, mandated by the Federal Records Act of 1950, as amended. The applicant is not required to retain a copy of the form. The FAA does not provide other persons or entities with information contained in the form.

Respondents: There were a total of 129 applications submitted to the FAA in fiscal year (FY) 2019. Out of the 129 applications, 64 applications were submitted for initial certification.

Frequency: Information is collected on occasion. One time for initial certification and when or if an existing certificated repair station request changes to their certificate.

Estimated Average Burden per Response: 15 minutes.

Estimated Total Annual Burden: 32.25 hours annual burden for FY2019. There is no requirement for a respondent to submit this form annually.

Issued in Washington, DC, on March 27, 2020.

Susan Traugott Ludwig,

Federal Aviation Administration, Office of Safety Standards, Aviation Safety Inspector, Aircraft Maintenance Division, Repair Station Branch, AFS-340.

[FR Doc. 2020-06750 Filed 3-31-20; 8:45 am]

BILLING CODE 4910-13-P

In addition, one copy of any comments submitted to the FAA must be mailed or delivered to: Greg Harrison, Winterset Airport Authority Chairman, Winterset Municipal Airport, 3405 N 8th Avenue, Winterset, IA 50273, (515) 468-0802.

FOR FURTHER INFORMATION CONTACT: Amy J. Walter, Airports Land Specialist, Federal Aviation Administration, Airports Division, ACE-620G, 901 Locust Room 364, Kansas City, MO 64106, (816) 329-2603, *amy.walter@faa.gov*.

The request to release property may be reviewed, by appointment, in person at this same location.

SUPPLEMENTARY INFORMATION: The FAA invites public comment on the request to release approximately 0.845± acres of airport property at the Winterset Municipal Airport (3Y3) under the provisions of 49 U.S.C. 47107(h)(2). On March 19, 2020, the Winterset Airport Authority Chairman requested from the FAA that 0.845± acres of property be released to Madison County for the purpose of relocating N. 8th Avenue and establishing a new right of way and utility corridor. On March 27, 2020, the FAA determined the request to release property at the Winterset Municipal Airport (3Y3) submitted by the Sponsor meets the procedural requirements of the Federal Aviation Administration and the release of the property does not and will not impact future aviation needs at the airport. The FAA may approve the request, in whole or in part, no sooner than thirty days after the publication of this Notice.

The following is a brief overview of the request:

Winterset Municipal Airport (3Y3) is proposing the release of a two parcels, totaling 0.845± acres. The release of land is necessary to comply with Federal Aviation Administration Grant Assurances that do not allow federally acquired airport property to be used for non-aviation purposes. The sale of the subject property will result in the land at the Winterset Municipal Airport (3Y3) being changed from aeronautical to nonaeronautical use and release the land from the conditions of the AIP Grant Agreement Grant Assurances. In accordance with 49 U.S.C. 47107(c)(2)(B)(i) and (iii), the airport will exchange these parcels for a parcel adjacent to the airport containing the previous N. 8th Avenue road right of way and utility corridor.

Any person may inspect, by appointment, the request in person at the FAA office listed above under **FOR FURTHER INFORMATION CONTACT.** In addition, any person may, upon

appointment and request, inspect the application, notice and other documents determined by the FAA to be related to the application in person at the Winterset Municipal Airport.

Issued in Kansas City, MO, on March 27, 2020.

James A. Johnson,
Director, Airports Division.

[FR Doc. 2020-06756 Filed 3-31-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

[Summary Notice No. 2020-14]

Petition for Exemption; Summary of Petition Received; Old Abe Aviation LLC

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice.

SUMMARY: This notice contains a summary of a petition seeking relief from specified requirements of Federal Aviation Regulations. The purpose of this notice is to improve the public's awareness of, and participation in, the FAA's exemption process. Neither publication of this notice nor the inclusion or omission of information in the summary is intended to affect the legal status of the petition or its final disposition.

DATES: Comments on this petition must identify the petition docket number and must be received on or before April 21, 2020.

ADDRESSES: Send comments identified by docket number FAA-2020-0056 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC 20590-0001, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at (202) 493-2251.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the