

Proposed Rules

Federal Register

Vol. 86, No. 61

Thursday, April 1, 2021

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0201; Project Identifier MCAI-2020-01346-T]

RIN 2120-AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. This proposed AD was prompted by a report of cracking in certain components on left and right sides of the aft wing-to-body fairing (WTBF) structure near the tie-rod attachment at a certain fuselage station; this cracking likely resulted from excessive tie-rod preload. This proposed AD would require inspecting the aft WTBF structure for any cracking or damage, adjusting the load on the two tie-rods at a certain fuselage station, and repair if necessary, as specified in a Transport Canada Civil Aviation (TCCA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 17, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact TCCA, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, Canada; telephone +1-888-663-3639; email AD-CN@tc.gc.ca; internet <https://tc.canada.ca/en/aviation>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0201.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0201; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0201; Project Identifier MCAI-2020-01346-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any

recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7330; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

TCCA, which is the aviation authority for Canada, has issued TCCA AD CF-2020-32, dated September 25, 2020 (TCCA AD CF-2020-32) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes.

This proposed AD was prompted by a report of cracking in the longeron, frame, and tie-rod on left and right sides of the aft WTBF structure near the tie-rod attachment at fuselage section (FS) 973. The cracking likely resulted from excessive tie-rod preload, and the cracking reportedly begins earlier on airplanes with the latest of the two aft WTBF configurations. The FAA is proposing this AD to address such cracking, which could lead to loss of aft WTBF integrity and result in damage due to parts departing the airplane, loss of the radio altimeter, and effects on airplane stability and performance. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

TCCA AD CF-2020-32 describes procedures for doing repetitive detailed visual inspections of the aft WTBF structure for any cracking or damage (including, but not limited to, cracking), adjusting the load on the two tie-rods at FS 973, reporting inspection results, and repairing any cracked or damaged WTBF structure. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in TCCA AD CF-2020-32 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and European Aviation Safety Agency (EASA) to develop a process to use certain EASA ADs as the primary

source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, TCCA AD CF-2020-32 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with TCCA AD CF-2020-32 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information specified in TCCA AD CF-2020-32 that is required for compliance with TCCA AD CF-2020-32 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0201 after the FAA final rule is published.

Interim Action

The FAA considers this proposed AD interim action. If final action is later identified, the FAA might consider further rulemaking then.

Costs of Compliance

The FAA estimates that this proposed AD affects 11 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS *

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
9 work-hours × \$85 per hour = \$765	\$0	\$765	\$8,415

* Table does not include estimated costs for reporting.

The FAA estimates that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the cost of reporting on U.S. operators to be \$935, or \$85 per product.

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information

required by this proposed AD is 2120-0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not

have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Docket No. FAA–2021–0201; Project Identifier MCAI–2020–01346–T.

(a) Comments Due Date

The FAA must receive comments by May 17, 2021.

(b) Affected Airworthiness Directives (ADs)

None.

(c) Applicability

This AD applies to all Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500–1A10 and BD–500–1A11 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of cracking in the longeron, frame, and tie-rod on left and right sides of the aft wing-to-body fairing (WTBF) structure near the tie-rod attachment at fuselage station (FS) 973; this

cracking likely resulted from excessive tie-rod preload. The FAA is issuing this AD to address such cracking, which could lead to loss of aft WTBF integrity and result in damage due to parts departing the airplane, loss of the radio altimeter, and effects on airplane stability and performance.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada Civil Aviation (TCCA) AD CF–2020–32, dated September 25, 2020 (TCCA AD CF–2020–32).

(h) Exceptions to TCCA AD CF–2020–32

(1) Where TCCA AD CF–2020–32 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraphs B. and E. of TCCA AD CF–2020–32 specify to repair “any cracks or damage” at certain compliance times or intervals, this AD requires repairing any cracks or damage before further flight.

(3) Where TCCA AD CF 2020–32 refers to hours air time, this AD requires using flight hours.

(4) Where table 1 of TCCA AD CF 2020–32 specifies a compliance time “for new aeroplanes with an aeroplane date of manufacture, as identified on the identification plate of the aeroplane, dated on or after the effective date of this AD” for this AD use “for airplanes with a date of manufacturer, as identified on the identification plate of the airplane, dated on or after the effective date of this AD.”

(5) Where TCCA AD CF 2020–32 defines the “applicable AMP DM” as “Airbus Canada Limited Partnership AMP DM BD500–A–J53–82–55–04AAA–720A–A (Aft fairing strut, Wing To Body Fairing (WTBF)—Install procedure) Issue 006, dated 26 June 2020, or later revisions,” for this AD use “Airbus Canada Limited Partnership AMP DM BD500–A–J53–82–55–04AAA–720A–A (Aft fairing strut, Wing To Body Fairing (WTBF)—Install procedure) Issue 006, dated 26 June 2020, or later-approved revisions.”

(6) Paragraph D. of TCCA AD CF–2020–32 specifies to report inspection results to Airbus Canada Limited Partnership within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(6)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the

procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch FAA; or TCCA; or Airbus Canada’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(3) *Paperwork Reduction Act Burden Statement:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory as required by this AD. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

(j) Related Information

(1) For information about TCCA AD CF–2020–32, contact TCCA, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, Canada; telephone 888–663–3639; email AD-CN@tc.gc.ca; Internet <https://tc.canada.ca/en/aviation>. You may find this TCCA AD on the TCCA website at <https://tc.canada.ca/en/aviation>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0201.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7330; fax 516–794–5531; email avs-nyaco-cos@faa.gov.

Issued on March 25, 2021.

Lance T. Gant,

*Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2021-06550 Filed 3-31-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 96

46 CFR Parts 71, 115, and 176

[Docket No. USCG-2020-0123]

RIN 1625-AC65

Safety Management Systems for Domestic Passenger Vessels

AGENCY: Coast Guard, DHS.

ACTION: Advance notice of proposed rulemaking; extension of comment period.

SUMMARY: The Coast Guard is extending the comment period for the advance notice of proposed rulemaking published January 15, 2021, that seeks comments on the potential use of Safety Management Systems to improve safety and reduce marine casualties on board U.S.-flagged passenger vessels. We are extending the comment period an additional 45 days, to June 1, 2021.

DATES: The comment period for the advance notice of proposed rulemaking published January 15, 2021, 86 FR 3899, is extended. Comments must be received by the Coast Guard on or before June 1, 2021.

FOR FURTHER INFORMATION CONTACT: For information about this document, call or email Lieutenant Kimberly Gates, Vessel and Facility Operating Standards Division (CG-OES-2), U.S. Coast Guard, 2703 Martin Luther King Jr. Avenue SE, Washington, DC 20593; telephone 202-372-1455, email kimberly.m.gates@uscg.mil.

SUPPLEMENTARY INFORMATION: The Coast Guard received a request to extend the comment period for an additional 45 days on its advance notice of proposed rulemaking (ANPRM) entitled "Safety Management Systems for Domestic Passenger Vessels," that was published January 15, 2021 (86 FR 3899). The requester cited ongoing COVID-19 impacts and that vessel owners and operators of the potentially affected population are impacted operationally. In response to this request, we are extending the comment period to June 1, 2021.

The Coast Guard is evaluating the potential use of Safety Management Systems (SMSs) to improve safety and reduce marine casualties on board U.S.-flagged passenger vessels. The ANPRM published January 15, 2021, seeks public input and responses to specific questions on the feasibility, applicability, and nature of Safety Management Systems for potential use on U.S.-flagged passenger vessels. The Coast Guard may use this information to develop a proposed rule.

On March 1, 2021, we published a correction (86 FR 11913) to one of the questions in the ANPRM. The corrected Question 19 now reads: "How would the costs and benefits of expanding other existing regulations, as detailed in question 6, differ from the costs and benefits of requiring SMSs for all passenger vessels?"

We encourage you to submit comments through the Federal eRulemaking Portal at <https://www.regulations.gov>. If you cannot submit your material by using <https://www.regulations.gov>, call or email the person in the **FOR FURTHER INFORMATION CONTACT** section of this document for alternate instructions.

The ANPRM and public comments in response to it are available in our online docket at <https://www.regulations.gov>, and can be viewed by following that website's instructions. We review all comments received, but we will only post comments that address the topic of the ANPRM. We may choose not to post off-topic, inappropriate, or duplicate comments that we receive. Additionally, if you visit the online docket and sign up for email alerts, you will be notified when comments or additional documents are posted. The Coast Guard will not issue a separate response to the comments received, but will carefully consider each comment and will address them in a proposed rule if one is developed.

We accept anonymous comments. Comments we post to <https://www.regulations.gov> will include any personal information you have provided. For more about privacy and submissions in response to this document, see the Department of Homeland Security's eRulemaking System of Records notice (85 FR 14226, March 11, 2020).

Dated: March 19, 2021.

M.T. Cunningham,

Chief, Office of Regulations and Administrative Law.

[FR Doc. 2021-06145 Filed 3-31-21; 8:45 am]

BILLING CODE 9110-04-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 110

[Docket Number USCG-2020-0620]

Anchorage Ground; Approaches to New York, Ambrose, Long Beach, NY

AGENCY: Coast Guard, DHS.

ACTION: Notification of inquiry; request for comments.

SUMMARY: We are requesting public comments regarding the potential establishment of an anchorage ground in an area referred to by mariners as the "Ambrose anchorage," which is an offshore area that has been used by ships awaiting inshore anchorages or berths. The area is located in the approaches to New York, approximately 3 nautical miles south of Long Beach, New York, and just north of the Nantucket to Ambrose Traffic Lane. The Coast Guard is considering formally establishing an anchorage ground at this location, possibly with regulations governing its use, if doing so will improve navigation safety and enhance safe and efficient flow of vessel traffic and commerce. We are seeking your comments on the benefits and impacts of establishing a regulated anchorage ground, and if so, what types of requirements we should consider for the Coast Guard oversight of the anchorage ground.

DATES: Your comments and related material must reach the Coast Guard on or before June 1, 2021. Commenters should be aware that the electronic Federal Docket Management System will not accept comments after midnight Eastern Daylight Time on the last day of the comment period. Although the Coast Guard prefers and highly encourages all comments and related material be submitted directly to the electronic docket, two virtual public meetings will be held via webinar and teleconference to provide an opportunity for oral comments regarding the possible establishment of an anchorage ground, often informally referred to as the "Ambrose anchorage" on Wednesday, April 21, 2021, beginning at 9 a.m. EST, and on Tuesday, April 27, 2021, beginning at 5 p.m. EST.

ADDRESSES: You may submit comments identified by docket number USCG-2020-0620 using the Federal portal at <https://www.regulations.gov>. See the "Public Participation and Request for Comments" portion of the **SUPPLEMENTARY INFORMATION** section for